



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI SE
Colour	Silver
Year of manufacture	2019
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	441 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	36.7 mpg
Consumption combined	30.4 mpg
CO2 emission	244 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-03-23
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	8
Total items failed	7

MOT #6	2023-08-16 09:32
MOT test number	339133528894
Result	✓ Passed
Next expiry date	2024-08-15
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Front Brake disc worn, but not excessively both sides lipped (1.1.14 (a) (i))

MOT #5	2023-08-16 09:32
MOT test number	770456622210
Result	✗ Failed
Advice	Front Brake disc worn, but not excessively both sides lipped (1.1.14 (a) (i))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Pass with rectification	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #4	2022-07-11 15:23
MOT test number	619888841432
Result	✓ Passed
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #3** 2022-07-11 15:23**MOT test number** 534678806445**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #2** 2022-04-06 16:57**MOT test number** 747016558216**Result** ✓ Passed**MOT #1** 2022-04-06 11:09**MOT test number** 331920980807**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
First licence fee (12 months)	£ 2.220,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 2.605,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-09-07
Last registration	2023-08-16
Complete history	See info



Registration #1	2019-09-07	7 mi
Registration #2	2019-09-07	29.312 mi
Registration #3	2022-04-06	29.313 mi
Registration #4	2022-04-06	29.315 mi
Registration #5	2019-09-07	29.317 mi
Registration #6	2019-09-07	29.317 mi
Registration #7	2019-09-07	29.317 mi
Registration #8	2019-09-07	29.317 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5150 mm
Wheel base	3200 mm
Max. allowed weight	3070 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2

Engine number

D4CBK773882