



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S AC
Colour	Blue
Year of manufacture	2013
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-10
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-07
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #9	2024-03-06 16:13
MOT test number	656908512503
Result	✓ Passed
Next expiry date	2025-03-07
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #8	2024-03-06 10:48
MOT test number	163708707885
Result	✗ Failed
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #7** 2023-03-06 08:53**MOT test number** 362303036952**Result** ✓ Passed**Advice** Rear Brake hose has slight corrosion to ferrule both sides (1.1.12 (f) (i))**Advice** Central Items removed from driver's view prior to test phone holder**Advice** Offside Rear Brake pipe corroded, covered in grease or other material on axle (corroded) (1.1.11 (c))**Advice** Parking brake efficiency only just met. it would appear that the braking system requires adjustment**MOT #6** 2022-03-08 14:24**MOT test number** 622193192764**Result** ✓ Passed**MOT #5** 2021-04-16 08:18**MOT test number** 183821447781**Result** ✓ Passed**MOT #4** 2019-05-08 17:14**MOT test number** 541249793006**Result** ✓ Passed**MOT #3** 2018-05-11 13:46**MOT test number** 197201764797**Result** ✓ Passed**MOT #2** 2017-05-11 10:16**MOT test number** 153479518838**Result** ✓ Passed



MOT #1	2016-05-11 08:59
MOT test number	398915402690
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-05-15
Last registration	2024-03-06
Complete history	See info



Registration #1	2013-05-15	24 mi
Registration #2	2016-05-11	15.302 mi
Registration #3	2017-05-11	22.869 mi
Registration #4	2018-05-11	30.101 mi
Registration #5	2019-05-08	35.315 mi
Registration #6	2021-04-16	38.096 mi
Registration #7	2022-05-20	39.277 mi
Registration #8	2023-05-20	39.277 mi
Registration #9	2023-05-20	39.277 mi
Registration #10	2023-05-20	39.277 mi
Registration #11	2024-03-06	39.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1000 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1635233