



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SE
Colour	Black
Year of manufacture	2007
Top speed	117 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk

Entry 1

Date	2021-02-05
Pictures	15
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2022-06-09
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	25
Total items failed	7

MOT #14	2021-06-10 12:00
MOT test number	604160222447
Result	✓ Passed
Next expiry date	2022-06-09
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2020-03-31 10:59
MOT test number	295352899110
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12	2018-12-06 17:51
MOT test number	132439847948
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-12-06 13:26**MOT test number** 753427316840**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2017-03-31 12:03**MOT test number** 731934979361**Result** ✓ Passed**Advice** Damage to front reg plate**MOT #9** 2017-03-28 10:13**MOT test number** 609634714789**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Damage to front reg plate**MOT #8** 2016-03-14 16:50**MOT test number** 656727486531**Result** ✓ Passed

**MOT #7** 2014-12-11 14:45**MOT test number** 249435944394**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2013-12-11 14:36**MOT test number** 498185843479**Result** ✓ Passed

- Notice** Front brake discs worn
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #5 2013-12-11 14:36**MOT test number** 898315243368**Result** ✗ Failed

- Notice** Front brake discs worn
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #4 2012-12-11 11:48**MOT test number** 885836842394**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2011-12-12 16:03**MOT test number** 189196541396**Result** ✓ Passed

Advice Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #2 2011-12-12 16:03**MOT test number** 447226641370**Result** ✗ Failed

Pass with rectification Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1 2010-12-09 10:25**MOT test number** 363243340363**Result** ✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-12-10
Last registration	2021-06-10
Complete history	See info



Registration #1	2007-12-10	12 mi
Registration #2	2010-12-09	74.514 mi
Registration #3	2011-12-12	80.982 mi
Registration #4	2012-12-11	92.489 mi
Registration #5	2013-12-11	106.652 mi
Registration #6	2014-12-11	122.068 mi
Registration #7	2016-03-14	137.582 mi
Registration #8	2017-03-28	146.308 mi
Registration #9	2018-03-28	155.034 mi
Registration #10	2019-03-28	163.760 mi
Registration #11	2020-03-28	172.486 mi
Registration #12	2021-03-28	181.212 mi
Registration #13	2022-03-28	189.938 mi
Registration #14	2023-03-28	198.664 mi
Registration #15	2024-03-28	207.390 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1616 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BXE 463592