






### General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history	
Entry 2	
Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

Entry 1	
Date	2021-01-21
Pictures	5
Listing price	<u>View report</u>



source: yesauto.com









# MOT history

MOT expiry date	2024-09-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #13	2023-09-08 12:38	
MOT test number	988299694196	
Result	🗸 Passed	
Next expiry date 2024-09		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))		

MOT #12		2023-09-08 12:38
MOT test number		923873492294
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #11		2022-06-20 09:43
MOT test	number	624094300765
Result		✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



MOT #10	2022-06-17 09:00	
MOT test number	328456857624	
Result	🗙 Failed	
Advice Rear exhaust back box corroded		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))		
Fail       Nearside Rear Position lamp not working (4.2.1 (a) (ii))		
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))		
Fail Horn not working (7.7 (a))		
Advice Oil leak, but not excessive gearbox oil leak (nsf drive shaft oil seal) (8.4.1 (a) (i)	))	

МОТ #9	2021-06-15 09:38
MOT test number	483461001421
Result	✓ Passed
Advice Offside Rear Nail in tyre	

МОТ #8	2021-06-14 15:44
MOT test number	709302130014
Result	🗙 Failed
Advice Offside Rear Nail in tyre	
Fail       Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Fail       Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #7	2020-10-23 12:17
MOT test number	201691203226
Result	✓ Passed





MOT #6	2020-02-12 11:00
MOT test number	223530294242
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
MOT #5	2019-02-18 11:10
MOT #5 MOT test number	2019-02-18 11:10 702855067611
MOT test number	702855067611

MOT #4	2018-02-23 14:03
MOT test number	216672091709
Result	✓ Passed
Advice Oil leak near gearbox area	

MOT #3	2018-02-23 11:04
MOT test number	570357888917
Result	🗙 Failed
Fail     Offside Headlamp not working on dipped beam (1.7.5a)       Fail     Nearside Front Broke pad(c) less than 1.5 mm thick (2.5.1g)	
FailNearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)AdviceOil leak near gearbox area	

MOT #2	2017-02-13 10:26
MOT test number	479250017700
Result	✓ Passed
Advice Osf wiper starting to deteriorate	





MOT #1	2016-02-24 15:04
MOT test number	354737544851
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	<b>MOT</b> <b>Expires:</b> 7 September 2024
Tax status	Valid until 1 September
Days left	126
MOT expiry date	7 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-11
Last registration	2023-09-08
Complete history	See info



Registration #1	2013-01-11	11 mi
Registration #2	2016-02-24	42.746 mi
Registration #3	2017-02-13	52.827 mi
Registration #4	2018-02-23	64.375 mi
Registration #5	2018-02-23	64.375 mi
Registration #6	2019-02-18	71.970 mi
Registration #7	2020-02-12	78.938 mi
Registration #8	2020-10-23	80.968 mi
Registration #9		11.117 esi
Registration #10		11.117 esi
Registration #11		11.117 esi
Registration #12		11.117 esi
Registration #13		11.117 esi
Registration #14		11.117 esi
Registration #15		11.117 esi
Registration #16		11.117 esi

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	0272619