





report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Red
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/12



RK60ZTD report date: 2024-03-28

Internet history

Entry	, 1
Ellel y	, -

ciitiy 1	
Date	2022-03-02
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-10
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	13
Total items failed	2

MOT #15	2024-03-11 16:21
MOT test number	871353057197
Result	✓ Passed
Next expiry date	2025-03-10
Advice Under trays fitted	

MOT #14		2024-03-11 12:10
MOT test	number	570367010384
Result		X Failed
MAJOR	Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice	Under trays fitted	

MOT #13		2023-03-08 11:47
MOT test	number	266550318800
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



MOT #10

RK60ZTD

report date: 2024-03-28

2021-11-16 16:16

MOT #12		2022-03-10 14:46
MOT test	number	936841381146
Result		✓ Passed
MOT #11		2022-03-09 14:34
MOT test	number	789811342784
Result		× Failed
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT test number	764645934945
Result	✓ Passed
MOT #9	2020-11-09 14:49
MOT test number	850117546694
Result	✓ Passed
MOT #8	2019-11-20 12:16
MOT test number	405660960794
Result	✓ Passed
Advice Front tyres getting low	
Advice Rear tyres wearing low and shallow cuts in tread	
Advice Rear shocker gaitors split	

MOT #7	2018-11-21 13:12
MOT test number	371716109645
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT test number

Fail

RK60ZTD

report date: 2024-03-28

399855114311

MOT #6

MOT test number

Result

Advice Front tyres wearing low

2017-11-25 09:44

435891299149

✓ Passed

 MOT #5
 2016-11-23 15:26

 MOT test number
 544534549164

 Result
 ✓ Passed

 MOT #4
 2015-11-16 12:56

 MOT test number
 830071774335

 Result
 ✓ Passed

MOT #3

MOT test number

859976114334

Result

✓ Passed

MOT #2 2014-11-11 12:13

Result × Failed

Pass with rectification Nearside Front Headlamp not working on main beam (1.7.5a)

Notice Advice tracking check

Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Notice All tyres wearing low

MOT #1 2013-11-05 06:27

MOT test number 966469503369


Result ✓ Passed

CarCheck.co.uk page 5/12



RK60ZTD report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CO. C.	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Mumber of prates	
Current registration	UK ZIS
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-20
Last registration	2024-03-11
Complete history	See info



Registration #1	2010-11-20	12 mi
Registration #2	2013-11-05	26.779 mi
Registration #3	2014-11-11	38.703 mi
Registration #4	2014-11-12	38.709 mi
Registration #5	2015-11-16	51.566 mi
Registration #6	2016-11-23	66.467 mi
Registration #7	2017-11-25	79.297 mi
Registration #8	2018-11-21	91.859 mi
Registration #9	2019-11-20	103.897 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1895 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	848865

CarCheck.co.uk page 12/12