



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 5 STR
Colour	Blue
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-14
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #16	2022-03-04 11:44
MOT test number	841289862831
Result	✓ Passed
Next expiry date	2023-03-07

MOT #15	2022-03-03 09:32
MOT test number	918766620355
Result	✗ Failed
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Front Side repeater not working (4.4.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2021-03-05 14:07
MOT test number	571672938420
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2020-03-02 09:10
MOT test number	889739983974
Result	✓ Passed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside rear tyre getting low on tread
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside rear brake disc showing signs of getting hot

**MOT #12** 2019-03-04 11:20**MOT test number** 785427975471**Result** ✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2018-03-07 11:39**MOT test number** 336756315931**Result** ✓ Passed

- Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Advice** Offside rear brake showing signs of getting hot
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #10 2017-03-08 07:21**MOT test number** 373565065110**Result** ✓ Passed**MOT #9** 2017-03-06 10:58**MOT test number** 341508226159**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)

MOT #8 2016-03-05 09:14**MOT test number** 489244929003**Result** ✓ Passed

**MOT #7** 2015-03-04 11:22**MOT test number** 176943765033**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components

MOT #6 2015-03-04 11:22**MOT test number** 109233465472**Result** ✗ Failed

- Notice** Under-trays fitted obscuring some underside components
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-03-06 11:45**MOT test number** 536575064061**Result** ✓ Passed**MOT #4** 2013-03-05 13:10**MOT test number** 279144063095**Result** ✓ Passed



MOT #3	2011-08-03 09:48
MOT test number	218205211264
Result	✓ Passed

MOT #2	2011-08-03 09:48
MOT test number	145525311283
Result	✗ Failed
<div>Pass with rectification</div> Tyre not fitted in accordance with side wall instructions (4.1.D.1f)	

MOT #1	2010-03-22 10:55
MOT test number	691371080081
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-21
Last registration	2022-03-04
Complete history	See info



Registration #1	2007-03-21	27 mi
Registration #2	2010-03-22	59.703 mi
Registration #3	2011-08-03	68.937 mi
Registration #4	2013-03-05	79.035 mi
Registration #5	2014-03-06	85.140 mi
Registration #6	2015-03-04	91.009 mi
Registration #7	2016-03-05	101.699 mi
Registration #8	2017-03-06	112.961 mi
Registration #9	2018-03-07	124.223 mi
Registration #10	2019-03-08	135.485 mi
Registration #11	2020-03-09	146.747 mi
Registration #12	2021-03-10	158.009 mi
Registration #13	2022-03-11	169.271 mi
Registration #14	2023-03-12	180.533 mi
Registration #15	2024-03-13	191.795 mi
Registration #16	2025-03-14	203.057 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD B25746