



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI 105
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-16
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	14
Total items failed	6

MOT #17 2023-08-16 10:32

MOT test number 463955449652

Result ✓ Passed

Next expiry date 2024-08-16

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #16 2022-08-17 15:44

MOT test number 440638050752

Result ✓ Passed

MOT #15 2022-08-17 13:31

MOT test number 904922145006

Result ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))

**MOT #14** 2021-06-02 14:15**MOT test number** 527299099134**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2021-05-27 16:12**MOT test number** 724183472228**Result** ✗ Failed**Fail** Offside Obligatory mirror missing glass (3.3 (a))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2020-06-24 09:36**MOT test number** 821458038995**Result** ✓ Passed**MOT #11** 2019-07-01 08:22**MOT test number** 334448790196**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-07-05 14:56**MOT test number** 851417976033**Result** ✓ Passed

**MOT #9** 2017-07-07 16:17**MOT test number** 953744921770**Result** ✓ Passed**Advice** Offside front tyre worn on inner edge on raised platform sections of tread**Advice** Nearside front tyre wearing on inner edges and starting to crack.**MOT #8** 2016-07-04 09:56**MOT test number** 932818873623**Result** ✓ Passed**MOT #7** 2015-07-17 13:03**MOT test number** 509768995198**Result** ✓ Passed**MOT #6** 2015-07-17 09:30**MOT test number** 959078595155**Result** ✗ Failed**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**MOT #5** 2014-07-24 12:33**MOT test number** 589855604275**Result** ✓ Passed



MOT #4	2013-07-26 10:46
---------------	------------------

MOT test number	907737703201
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
---------------	--

MOT #3	2012-09-27 17:15
---------------	------------------

MOT test number	907331372241
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-08-03 09:50
---------------	------------------

MOT test number	715696212263
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2011-06-21 11:35
---------------	------------------

MOT test number	158372071129
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
16 August 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VA08GWN
Plate since	2019-06-29
Current registration	 VA08GWN
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-14
Last registration	2023-08-16
Complete history	See info



Registration #1	2008-07-14	7 mi
Registration #2	2011-06-21	26.289 mi
Registration #3	2012-08-03	35.753 mi
Registration #4	2012-09-27	35.805 mi
Registration #5	2013-07-26	38.555 mi
Registration #6	2014-07-24	43.582 mi
Registration #7	2015-07-17	48.444 mi
Registration #8	2015-07-17	48.444 mi
Registration #9	2016-07-04	53.009 mi
Registration #10	2017-07-07	57.133 mi
Registration #11	2018-06-21	57.133 mi
Registration #12	2019-06-21	57.133 mi
Registration #13	2020-06-21	57.133 mi
Registration #14	2021-06-21	57.133 mi
Registration #15	2022-06-21	57.133 mi
Registration #16	2023-06-21	57.133 mi
Registration #17	2024-06-21	57.133 mi
Registration #18	2025-06-21	57.133 mi
Registration #19	2026-06-21	57.133 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1251 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE B29276