



General information

Make	MINI
Model	ONE AUTO ONE
Colour	White
Year of manufacture	2013
Top speed	108 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-10-20
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-09-17
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	21
Total items failed	20

MOT #18 2024-09-16 15:11

MOT test number 562422422881

Result ✔ Passed

Next expiry date 2025-09-17

Minor Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #17 2024-09-14 11:43

MOT test number 105325605898

Result ✘ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #16 2023-09-18 16:55

MOT test number 359499243358

Result ✔ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))



MOT #15	2023-09-15 11:21
MOT test number	608763138118
Result	✗ Failed
Fail	Offside Front Windscreen washer not working (3.5 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MOT #14	2022-09-01 14:11
MOT test number	920447592347
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2022-09-01 09:37
MOT test number	847123462265
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))



MOT #12	2021-08-19 14:21
MOT test number	756016988778
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear brake pad warning wire not connected

MOT #11	2021-08-13 11:16
MOT test number	113178012998
Result	✗ Failed
Fail	Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Rear brake pad warning wire not connected
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Nearside Front Road wheel fractured (5.2.2 (a))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10	2020-09-02 09:49
MOT test number	259071483287
Result	✓ Passed

MOT #9	2020-09-02 09:49
MOT test number	582384254052
Result	✗ Failed
Pass with rectification	Brake warning device not identifying low pressure (1.1.4 (a) (ii))



MOT #8 2019-08-06 12:40
MOT test number 388681829940
Result ✔ Passed
Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #7 2018-08-06 11:21
MOT test number 774026215507
Result ✔ Passed

MOT #6 2018-08-06 11:21
MOT test number 984210980290
Result ✘ Failed
Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #5 2017-08-26 10:05
MOT test number 109287297236
Result ✔ Passed

MOT #4 2017-08-26 08:10
MOT test number 953510082232
Result ✘ Failed
Fail Offside Headlamp not working on dipped beam (1.7.5a)
Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2016-09-23 10:23
MOT test number 360212068901
Result ✔ Passed
Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #2 2016-09-23 10:23

MOT test number 304943980509

Result ✗ Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Nearside Headlamp not working on main beam (1.7.5a)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #1 2015-09-25 15:00

MOT test number 319180512163

Result ✓ Passed



Tax & MOT check

×
Untaxed

Tax expired:
8 October 2024

✓
MOT

Expires:
17 September 2025

Tax status	Expired at 8 October 2024
Days left	4 days too late
MOT expiry date	17 September 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	LT130WW
Plate since	2019-09-29
Current registration	LT130WW
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2013-03-07
Last registration	2024-09-16
Complete history	See info



Registration #1	2013-03-07	16 mi
Registration #2	2015-09-25	24.354 mi
Registration #3	2016-09-23	40.999 mi
Registration #4	2016-09-23	40.999 mi
Registration #5	2017-08-26	52.659 mi
Registration #6	2017-08-26	52.659 mi
Registration #7	2018-08-06	66.024 mi
Registration #8	2018-08-06	66.024 mi
Registration #9	2019-08-06	80.968 mi
Registration #10	2020-09-02	96.851 mi
Registration #11	2020-09-02	96.851 mi
Registration #12	2020-09-02	96.851 mi
Registration #13	2020-09-02	96.851 mi
Registration #14	2020-09-02	96.851 mi
Registration #15	2020-09-02	96.851 mi
Registration #16	2020-09-02	96.851 mi
Registration #17	2020-09-02	96.851 mi
Registration #18	2020-09-02	96.851 mi
Registration #19	2020-09-02	96.851 mi
Registration #20	2024-09-16	160.000 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

A092J333