



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | FIAT |
| Model | PANDA POP |
| Colour | White |
| Year of manufacture | 2013 |
| Top speed | 102 mph |
| 0 - 60 mph | 14.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 69 BHP |
| Max. torque | 102 Nm at 3.000 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 120 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 3 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-06 |
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 24 |
| Total items failed | 5 |

MOT #10 2024-02-07 15:30

MOT test number 375680658620

Result ✓ Passed

Next expiry date 2025-02-06

Advice Offside Front Tyre worn close to legal limit/worn on edge ** WORN TO 2.5MM ** (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Nail in tyre Outer edge

MOT #9 2024-02-07 09:10

MOT test number 152369499628

Result ✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge ** WORN TO 2.5MM ** (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Nail in tyre Outer edge

MOT #8 2023-01-13 11:05

MOT test number 109103274821

Result ✓ Passed

**MOT #7** 2021-11-04 11:10**MOT test number** 240241985834**Result** ✓ Passed**Advice** Rear Coil spring corroded both rear springs have slight corrosion at the base (5.3.1 (b) (i))**MOT #6** 2020-09-24 14:43**MOT test number** 903080933834**Result** ✓ Passed**Advice** Exhaust corroded**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #5** 2020-09-24 10:27**MOT test number** 844360229994**Result** ✗ Failed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Exhaust corroded**Fail** Nearside Front Service brake lagging in operation (1.2.1 (d))**Fail** Offside Rear Shock absorbers has an excessively worn bush top bush (5.3.2 (c))

**MOT #4** 2019-09-25 08:46**MOT test number** 785890008142**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge close to limit (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge close to limit (5.2.3 (e))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords perished/splitting (5.2.3 (d) (i))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #3 2018-09-12 09:50**MOT test number** 632731848691**Result** ✓ Passed

- Advice** Offside Rear Suspension component pin or bush slightly worn top shock bush (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension component pin or bush slightly worn top shock bush (5.3.4 (a) (i))

MOT #2 2017-09-29 09:56**MOT test number** 724688868300**Result** ✓ Passed**MOT #1** 2016-11-24 11:27**MOT test number** 181564587083**Result** ✓ Passed

- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Advise strong offside front tyre badly worn on edges and close to limit
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Advise strong nearside front tyre badly worn on edges and close to limit



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
6 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 277 |
| MOT expiry date | 6 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|----------------|
| Vehicle class | 48 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this FIAT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | KX63BBN |
| Plate since | 2019-09-29 |
| Current registration | KX63BBN |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2013-10-26 |
| Last registration | 2024-02-07 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-10-26 | 12 mi |
| Registration #2 | 2016-11-24 | 20.918 mi |
| Registration #3 | 2017-09-29 | 26.129 mi |
| Registration #4 | 2018-09-12 | 31.922 mi |
| Registration #5 | 2019-09-25 | 38.179 mi |
| Registration #6 | 2020-09-24 | 42.190 mi |
| Registration #7 | 2020-09-24 | 42.190 mi |
| Registration #8 | 2020-09-24 | 42.190 mi |
| Registration #9 | 2020-09-24 | 42.190 mi |
| Registration #10 | 2020-09-24 | 42.190 mi |
| Registration #11 | 2020-09-24 | 42.190 mi |
| Registration #12 | 2020-09-24 | 42.190 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 82% |
| Children | 63% |
| Pedestrian | 49% |
| Safety systems | 43% |
| Overall rating | 68% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1882 mm |
| Height | 1551 mm |
| Length | 3653 mm |
| Wheel base | 2300 mm |
| Max. allowed weight | 1420 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 37 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |

Engine number

0341597