





### General information

Make	VOLVO
Model	S60 D4 SE NAV
Colour	Silver
Year of manufacture	-
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg





Internet history			
ntry 1			
Date	2021-07-2	27	
Pictures	9		
Listing price	View repo	ort	
APPROVED DEALERSHIP WITH DEALERSHIP WITH DEALERSHIP WARRANTES MARKANES	<image/> <section-header><section-header><section-header><text></text></section-header></section-header></section-header>	EVE VILLAGE CARS NEW ARRIVAL Detes Conving Score Call For Details	COMPARENT REAL AND A COMPARENT





### MOT history

MOT #6	2021-12-14 14:15
MOT test number	377608436721
Result	✓ Passed
Next expiry date	2022-12-13

MOT #5		2021-12-14 14:15
MOT test number		404633686251
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	

MOT #4	2020-08-14 16:0	
MOT test	number 579970981043	;
Result	✓ Passed	ł
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)	

MOT #3		2019-08-27 09:06
MOT test	number	573881515735
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm and worn on i	nner edge (5.2.3 (e))
Advice (e))	Offside Rear Tyre worn close to legal limit/worn on edge tyre worn unevenly	on inner edge (5.2.3
Advice (e))	Nearside Front Tyre worn close to legal limit/worn on edge 2mm and worn or	n inner edge (5.2.3
<b>Advice</b> (5.2.3 (e))	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm and worn un	evenly on inner edge
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #2	2018-08-16 09:33
MOT test number	822492052882
Result	✓ Passed





2017-08-30 09:10
627259726561
✓ Passed





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K K
Damage 2	AMPL
	F Store
Date	 1. F
Category	 ant
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	
***********	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Current registration Pate since	





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2014-09-02
Last registration	2021-12-14
Complete history	See info



Registration #1	2014-09-02	22 mi
Registration #2	2017-08-30	72.830 mi
Registration #3	2018-08-16	78.483 mi
Registration #4	2019-08-27	100.072 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		10.300 est





### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight	
Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1660 kg
Max. allowed weight	2200 kg
Additional information	
Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/10