



TOYOTA

HV55XWG

report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Silver
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-10-21
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-02-17
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	33
Total items failed	11

MOT #20	2021-02-06 16:48
MOT test number	417628423720
Result	✓ Passed
Next expiry date	2022-02-17
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #19	2021-02-06 12:08
MOT test number	240251651299
Result	✗ Failed
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 21 % (1.2.1 (b) (i))
Fail	Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Fail	Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #18**

2020-02-07 11:50

MOT test number

535577678078

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #17**

2020-02-05 09:26

MOT test number

935927512227

Result

✗ Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #16**

2019-02-06 16:14

MOT test number

481390441255

Result

✓ Passed

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Advice** Rear Brake hose slightly deteriorated Both (1.1.12 (b) (ii))

**MOT #15** 2019-02-06 15:25**MOT test number** 786747751572**Result** ✗ Failed**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Rear Brake hose slightly deteriorated Both (1.1.12 (b) (ii))**MOT #14** 2018-02-07 13:12**MOT test number** 857046170383**Result** ✓ Passed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #13** 2018-02-07 09:50**MOT test number** 485045524744**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. parking (3.7.B.5b)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #12** 2017-02-10 11:34**MOT test number** 291847972049**Result** ✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #11 2017-02-09 15:17**MOT test number** 419759077681**Result** ✗ Failed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Fail Rear rear parking (secondary) brake grabbing severely (3.7.B.6b)

MOT #10 2016-02-18 13:01**MOT test number** 108644167685**Result** ✓ Passed**MOT #9** 2016-02-18 11:16**MOT test number** 685650210245**Result** ✗ Failed

Fail Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

Fail Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)

MOT #8 2014-08-28 16:49**MOT test number** 357660844416**Result** ✓ Passed**MOT #7** 2013-08-30 10:49**MOT test number** 655692843282**Result** ✓ Passed

**MOT #6** 2012-09-14 12:16**MOT test number** 329768852460**Result** ✓ Passed**MOT #5** 2012-09-14 12:16**MOT test number** 569708452208**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #4** 2011-09-09 10:35**MOT test number** 256222451276**Result** ✓ Passed**MOT #3** 2010-09-15 14:27**MOT test number** 422328750270**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front discs wearing thin**MOT #2** 2009-09-29 10:07**MOT test number** 170832479236**Result** ✓ Passed**Notice** Rear brake pads low**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2008-09-19 14:36
MOT test number	502683168290
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
20 October 2021

X

MOT

Expired:
17 February 2022

Tax status	Expired at 20 October 2021
Days left	923 days too late
MOT expiry date	17 February 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	HV55XWG
Plate since	2019-03-29
Current registration	HV55XWG
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-27
Last registration	2021-02-06
Complete history	See info



Registration #1	2005-09-27	14 mi
Registration #2	2008-09-19	37.977 mi
Registration #3	2009-09-29	50.369 mi
Registration #4	2010-09-15	62.673 mi
Registration #5	2011-09-09	75.953 mi
Registration #6	2012-09-14	90.089 mi
Registration #7	2013-08-30	100.570 mi
Registration #8	2014-08-28	112.537 mi
Registration #9	2016-02-18	123.433 mi
Registration #10	2016-02-18	123.433 mi
Registration #11	2017-02-09	128.763 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi
Registration #17	2019-05-29	151.377 mi
Registration #18	2019-05-29	151.377 mi
Registration #19	2019-05-29	151.377 mi
Registration #20	2019-05-29	151.377 mi
Registration #21	2019-05-29	151.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

4ZZU640926