



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 E4 D SE V50
Colour	Silver
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2021-01-14
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	41
Total items failed	15

MOT #17	2020-01-15 15:58
MOT test number	593923176623
Result	✓ Passed
Next expiry date	2021-01-14

MOT #16	2020-01-15 08:55
MOT test number	273647223352
Result	✗ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #15	2018-12-05 16:53
MOT test number	743150632922
Result	✓ Passed

MOT #14	2017-10-02 14:47
MOT test number	869537264567
Result	✓ Passed

**MOT #13**

2017-10-02 08:32

MOT test number

558484551986

Result**✗ Failed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Steering rack insecure (2.2.B.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12**

2016-09-06 15:01

MOT test number

782899611353

Result**✓ Passed****Advice** Nearside front and offside front tyres worn on inner edges**Advice** Rear brake back plates deteriorated**Advice** Exhaust deteriorated**Advice** Nearside and offside rear lower suspension buses are very slightly worn**MOT #11**

2016-08-23 09:42

MOT test number

261480841325

Result**✗ Failed****Advice** Rear brake back plates deteriorated**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**Advice** Exhaust deteriorated**Advice** Nearside and offside rear lower suspension buses are very slightly worn**Fail** Exhaust system not adequately supported (7.1.1)**Advice** Nearside front and offside front tyres worn on inner edges

**MOT #10**

2015-09-03 14:37

MOT test number

427469901062

Result

✓ Passed

- Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Advice** Engine covers fitted
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Undertrays fitted

MOT #9

2015-09-03 10:18

MOT test number

387268196954

Result

✗ Failed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Engine covers fitted
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Fail** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm edge (4.1.E.1)
- Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)
- Advice** Undertrays fitted
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Offside Rear Inner Tyre tread depth below requirements of 1.6mm edge (4.1.E.1)

**MOT #8** 2014-09-03 09:47**MOT test number** 246936044239**Result** ✓ Passed

- Notice** Front tyres worn on edges
- Notice** Rear brake hoses protective cover deteriorated
- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #7 2013-09-06 12:12**MOT test number** 325889843222**Result** ✓ Passed

- Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2012-09-07 16:41**MOT test number** 359551152220**Result** ✓ Passed

- Notice** Child seats fitted to nearside and offside rear, preventing inspection of seat belts.

MOT #5 2012-09-07 12:48**MOT test number** 485831852284**Result** ✗ Failed

- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Child seats fitted to nearside and offside rear, preventing inspection of seat belts.
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Rear brake caliper leaking (3.6.A.1)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #4**

2011-09-07 15:54

MOT test number

378660451457

Result

✓ Passed

- Notice** Nearside and offside front tyres are worn on inner egdes
- Notice** Child seat fitted to nearside rear, preventing inspection of seat belt.
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Nearside and offside front brake discs are worn

MOT #3

2011-09-07 10:34

MOT test number

306170051470

Result

✗ Failed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Child seat fitted to nearside rear, preventing inspection of seat belt.
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Nearside and offside front brake discs are worn
- Fail** Nearside Rear Suspension arm attachment bracket/mounting bolt missing (2.4.G.1)
- Notice** Nearside and offside front tyres are worn on inner egdes

MOT #2

2010-08-19 14:29

MOT test number

562891630246

Result

✓ Passed

- Notice** Nail in nearside rear tyre
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2009-09-10 08:35
MOT test number	231963459275
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	OX06GME
Plate since	2019-09-28
Current registration	OX06GME
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-07-31
Last registration	2020-01-15
Complete history	See info



Registration #1	2006-07-31	22 mi
Registration #2	2009-09-10	34.630 mi
Registration #3	2010-08-19	48.113 mi
Registration #4	2011-09-07	59.782 mi
Registration #5	2011-09-07	59.782 mi
Registration #6	2012-09-07	72.661 mi
Registration #7	2012-09-07	72.661 mi
Registration #8	2013-09-06	85.277 mi
Registration #9	2014-09-03	96.560 mi
Registration #10	2015-09-03	107.843 mi
Registration #11	2016-09-03	119.126 mi
Registration #12	2017-09-03	130.409 mi
Registration #13	2018-09-03	141.692 mi
Registration #14	2019-09-03	152.975 mi
Registration #15	2020-01-15	164.258 mi
Registration #16		
Registration #17		
Registration #18		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4014833