





report date: 2024-03-28

#### General information

Make	VOLVO
Model	XC60 D5 SE LUX AWD
Colour	Red
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date	2021-06-05
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-07
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	24
Total items failed	5

MOT #14	2024-04-04 08:32
MOT test number	745922060902
Result	✓ Passed
Next expiry date	2025-04-07
Advice Emissions to clean to register	

MOT #13	2023-03-20 08:37
MOT test number	647867286301
Result	<b>✓</b> Passed

MOT #12	2022-03-30 10:16
MOT test number	940539172303
Result	✓ Passed

MOT #11	2021-03-22 16:34
MOT test number	301358034760
Result	✓ Passed
Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

CarCheck.co.uk page 3/13



**MOT #10** 2021-03-22 11:31

**MOT test number** 503883155646

Result X Failed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9 2020-03-24 10:24

**MOT test number** 455568692334

**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-04-08 13:34

**MOT test number** 800527226745

**Result** ✓ Passed

MOT #7 2018-08-01 14:10

**MOT test number** 528394775725

Result \rightarrow Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2017-08-03 08:23 **MOT** test number 463911992691 Result × Failed Front Brake pad(s) wearing thin (3.5.1g) **Advice** Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Rear fog lamp not working (1.3.2b) **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Registration plate lamp not working (1.1.C.1d)

MOT #4	2016-08-19 16:32
MOT test number	960059958429
Result	✓ Passed
MOT #3	2015-08-01 12:26
MOT test number	355783615230
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2		2014-08-22 11:00
MOT test	number	346304734417
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2013-09-30 15:57
MOT test number	797083073208
Result	<b>√</b> Passed

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	7 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
O WILCI	,

,		
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full		)
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK MAN	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-24
Last registration	2024-04-04
Complete history	See info



Registration #1	2010-09-24	10 mi
Registration #2	2013-09-30	52.953 mi
Registration #3	2014-08-22	64.256 mi
Registration #4	2015-08-01	76.178 mi
Registration #5	2016-08-19	89.952 mi
Registration #6	2017-08-03	102.014 mi
Registration #7	2017-08-03	102.015 mi
Registration #8	2018-08-01	114.528 mi
Registration #9		71,777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1885 kg
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number 906633