





report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOKKA ACTIVE
Colour	Silver
Year of manufacture	2018
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 1.850 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	52.3 mpg
Consumption combined	43.5 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-17

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



FY18PGU

report date: 2024-03-29

MOT history

MOT expiry date	2025-04-06
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	26
Total items failed	3

MOT #7		2024-04-05 15:48
MOT test	number	624891040471
Result		✓ Passed
Next expi	y date	2025-04-06
Advice	Exhaust flexi broke	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2024-04-05 09:03	
MOT test	number 909315033816	
Result	▼ Failed	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR (5.3.4 (b) (
Advice	Exhaust flexi broke	
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 3/12



FY18PGU

report date: 2024-03-29

MOT #5 2023-03-28 10:37

MOT test number 332104487462

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Coolant leak

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

MOT #4 2023-03-28 08:55

MOT test number 183567062927

Result X Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Coolant leak

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/12



Pass with rectification

Result

FY18PGU

report date: 2024-03-29

X Failed

MOT #3 2022-04-04 09:01

488724517105 **MOT** test number

✓ Passed Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #2 2022-04-04 09:01

MOT test number 830258882697

Windscreen washer not working (3.5 (a))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Advice

Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2021-04-07 11:27

MOT test number 405148330321

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category


Type

Damage 2

Date

Category

Extra VAUXHALL salvage check





Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

2000000	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-30
Last registration	2024-04-05
Complete history	See info



Registration #1	2018-05-30	10 mi
Registration #2	2021-04-07	11.481 mi
Registration #3		91,777 esi
Registration #4	2022-04-04	21.320 mi
Registration #5	2022-04-04	21.320 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 11/12



FY18PGU

report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1658 mm
Length	4275 mm
Wheel base	2555 mm
Kerb weight	1334 kg
Max. allowed weight	1843 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14NET 180320704LUJ

CarCheck.co.uk page 12/12