



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 POWERPULSE MOMENTUM AWD
Colour	Blue
Year of manufacture	2017
Top speed	137 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	52.3 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-05
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	19
Total items failed	2

MOT #6	2023-06-15 08:05
MOT test number	455215662349
Result	✓ Passed
Next expiry date	2024-06-27
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Minor	Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #5	2023-06-15 08:05
MOT test number	196191651405
Result	✗ Failed
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Minor	Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #4** 2022-06-28 14:21**MOT test number** 949732615367**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt Ns/Os**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2022-06-28 09:33**MOT test number** 798270468858**Result** ✗ Failed**Fail** Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt Ns/Os**MOT #2** 2021-02-08 11:49**MOT test number** 937016826097**Result** ✓ Passed**Advice** Engine trims fitted**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Under trays fitted**Advice** Front tyres 3-4 mm



MOT #1	2020-02-24 11:47
MOT test number	198371604759
Result	✓ Passed
Advice	Engine trims fitted
Advice	Under trays fitted
Advice	Front tyres 4 mm



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
27 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-08
Last registration	2023-06-15
Complete history	See info



Registration #1	2017-03-08	24 mi
Registration #2	2020-02-24	32.957 mi
Registration #3	2021-02-08	38.935 mi
Registration #4	2022-02-08	39.957 mi
Registration #5	2022-02-08	39.957 mi
Registration #6	2022-02-08	39.957 mi
Registration #7	2022-02-08	39.957 mi
Registration #8	2023-06-15	39.957 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Wheel base	2984 mm
Kerb weight	2009 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1987511