



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D SE
Colour	Black
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-04
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-04
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	35
Total items failed	3

MOT #19 2024-01-23 12:41

MOT test number 274382575823

Result ✓ Passed

Next expiry date 2025-02-04

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Rear Trailing arm bush (5.3.4 (a) (i))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated Inner joint (6.1.7 (g) (i))

MOT #18 2023-02-03 14:42

MOT test number 706430580953

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17** 2023-02-03 10:10**MOT test number** 687605128830**Result** ✗ Failed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16** 2022-01-28 10:45**MOT test number** 329248332158**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2021-01-25 15:17**MOT test number** 449223440789**Result** ✓ Passed**MOT #14** 2021-01-25 09:56**MOT test number** 676604682683**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #13** 2020-01-23 13:35**MOT test number** 716174094445**Result** ✓ Passed

**MOT #12** 2019-01-28 10:18**MOT test number** 259358376046**Result** ✓ Passed**MOT #11** 2018-02-05 15:21**MOT test number** 892989958263**Result** ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' slightly scored (8.3.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (3.5.1i)
- Advice** Offside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

MOT #10 2018-02-05 15:21**MOT test number** 757058777940**Result** ✗ Failed

- Pass with rectification** Offside Front Headlamp aim too high (1.8)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c)
- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' slightly scored (8.3.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (3.5.1i)
- Advice** Offside Rear Coil spring mounting corroded but not seriously weakened (2.4.C.3c)

**MOT #9** 2017-02-04 09:25**MOT test number** 735916014116**Result** ✓ Passed**MOT #8** 2016-03-09 11:34**MOT test number** 479538495716**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #7 2015-09-02 10:03**MOT test number** 417722547249**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front washer slightly blocked
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front marker light inop

MOT #6 2014-09-08 11:03**MOT test number** 158661254295**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #5 2013-09-05 14:37**MOT test number** 139978243200**Result** ✓ Passed



MOT #4	2012-08-30 15:47
MOT test number	527803742259
Result	✓ Passed
MOT #3	2011-09-06 12:22
MOT test number	389529841414
Result	✓ Passed
MOT #2	2010-09-16 14:44
MOT test number	204889050222
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
MOT #1	2010-08-03 16:51
MOT test number	654635110272
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
4 February 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BN57HPY
Plate since	2024-03-28
Current registration	BN57HPY
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-12
Last registration	2024-01-23
Complete history	See info



Registration #1	2007-09-12	19 mi
Registration #2	2010-08-03	24.682 mi
Registration #3	2010-09-16	25.773 mi
Registration #4	2011-09-06	28.311 mi
Registration #5	2012-08-30	33.204 mi
Registration #6	2013-09-05	40.065 mi
Registration #7	2014-09-08	45.976 mi
Registration #8	2015-09-02	52.359 mi
Registration #9	2016-03-09	56.180 mi
Registration #10	2017-02-04	62.330 mi
Registration #11	2018-02-05	79.817 mi
Registration #12	2019-05-20	95.557 mi
Registration #13	2020-05-20	105.557 mi
Registration #14	2021-05-20	115.557 mi
Registration #15	2022-05-20	125.557 mi
Registration #16	2023-05-20	135.557 mi
Registration #17	2024-01-23	145.557 mi
Registration #18	2024-01-23	155.557 mi
Registration #19	2024-01-23	165.557 mi
Registration #20	2024-01-23	175.557 mi
Registration #21	2024-01-23	185.557 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1490 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1583 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	521398