



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 R-DESIGN LUX NAV
Colour	White
Year of manufacture	2015
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	View report

source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-22
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	6

MOT #8	2024-01-15 12:02
MOT test number	621510289451
Result	✓ Passed
Next expiry date	2025-01-22
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/60/18 (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 235/60/18 (5.2.3 (e))

MOT #7	2024-01-15 12:02
MOT test number	595047270814
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/60/18 (5.2.3 (e))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 235/60/18 (5.2.3 (e))

MOT #6	2023-01-23 13:07
MOT test number	729701283782
Result	✓ Passed

**MOT #5** 2023-01-17 10:05**MOT test number** 715872263733**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 235/60/18 (5.2.3 (e))**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm 235/60/18 (5.2.3 (e))**MOT #4** 2022-01-20 16:21**MOT test number** 907053343419**Result** ✓ Passed**Advice** Power steering close to minimum mark (2.1.5 (b) (i))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #3** 2021-01-20 15:22**MOT test number** 998475251336**Result** ✓ Passed**MOT #2** 2019-07-03 11:05**MOT test number** 253651393953**Result** ✓ Passed



MOT #1	2018-06-30 08:08
MOT test number	715796429378
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
22 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	22 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-17
Last registration	2024-01-15
Complete history	See info



Registration #1	2015-07-17	18 mi
Registration #2	2018-06-30	39.537 mi
Registration #3	2019-07-03	49.804 mi
Registration #4	2021-01-20	57.916 mi
Registration #5	2022-05-20	65.277 mi
Registration #6	2023-05-20	75.277 mi
Registration #7	2023-05-20	85.277 mi
Registration #8	2023-05-20	95.277 mi
Registration #9	2023-05-20	105.277 mi
Registration #10	2024-01-15	118 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1790 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1217988