



VN09GGZ

report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Black
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg





Internet history

Entry 1

Date	2021-01-30
Pictures	9
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history****MOT #14**

2024-03-04 15:49

**MOT test number**

928241867782

**Result****✗ Failed**

- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Nearside Non obligatory mirror damaged
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play top mount (5.3.4 (a) (i))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2023-02-04 12:00

**MOT test number**

844532015288

**Result****✓ Passed**

- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #12** 2022-01-28 13:47**MOT test number** 877766137062**Result** ✓ Passed**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-01-29 15:45**MOT test number** 236339971612**Result** ✓ Passed**MOT #10** 2019-12-05 16:26**MOT test number** 506039876996**Result** ✓ Passed**MOT #9** 2018-11-08 14:01**MOT test number** 348760641803**Result** ✓ Passed**MOT #8** 2018-08-07 11:26**MOT test number** 465879479779**Result** ✓ Passed**MOT #7** 2017-08-08 10:04**MOT test number** 793160091187**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases clamp corroded (7.1.2)

**MOT #6** 2017-08-07 08:48**MOT test number** 489175519092**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases clamp corroded (7.1.2)**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm 175/65/14 (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-08-09 15:58**MOT test number** 372067441444**Result** ✓ Passed**MOT #4** 2015-07-09 14:00**MOT test number** 718440895189**Result** ✓ Passed**Advice** Offside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Rear exhaust outer skin deteriorated**MOT #3** 2014-07-21 09:40**MOT test number** 908042404256**Result** ✓ Passed**MOT #2** 2013-07-25 09:33**MOT test number** 805086403206**Result** ✓ Passed



MOT #1	2012-07-24 16:36
MOT test number	675786602234
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXX XX</b>
Plate since	2024-03-28
Current registration	<b>XXXX XX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-16
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2009-06-16	19 mi
Registration #2	2012-07-24	24.617 mi
Registration #3	2013-07-25	32.219 mi
Registration #4	2014-07-21	51.986 mi
Registration #5	2015-07-09	56.108 mi
Registration #6	2016-08-09	60.315 mi
Registration #7	2017-08-07	63.543 mi
Registration #8	2017-08-08	63.548 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5187434