



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S HDI
Colour	Silver
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.3 mpg
Consumption extra urban	70.5 mpg
Consumption combined	62.7 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2021-06-24
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-07
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT #23	2022-05-05 15:26
MOT test number	515633540516
Result	✓ Passed
Next expiry date	2023-05-04
Advice Front anti roll bar links have slight play-all tyres feathering/perished/worn low-both front coil springs corroded-wishbone bushes deteriorated-n/s/f cv boot deteriorated-rear brakes slightly binding	
Advice Rear Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))	
Advice Sills corroded/weak-parking brake lever slight travel-oil leak-front brake discs and pads worn thin-both rear coil springs corroded-exhaust smoking when cold-engine/gearbox mountings deteriorated	
Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))	

MOT #22	2020-10-23 11:22
MOT test number	412736656046
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #21	2019-03-26 19:45
MOT test number	999378396191
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #20	2019-03-25 18:36
MOT test number	934946734184
Result	✗ Failed
Fail Coil spring fractured or broken both rear (5.3.1 (b) (i))	
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

**MOT #19** 2018-04-25 14:24**MOT test number** 976249026483**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #18** 2017-04-08 10:16**MOT test number** 412371522524**Result** ✓ Passed**Advice** Injector passing**Advice** Nearside Rear Nail in tyre**MOT #17** 2017-04-08 08:52**MOT test number** 166090080336**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Injector crack**Fail** Battery insecure (1.9.1)**MOT #16** 2016-04-16 10:11**MOT test number** 952010901551**Result** ✓ Passed**Advice** Engine noise**Advice** Front number plate detriating

**MOT #15**

2015-04-18 11:11

MOT test number

899718305147

Result

✓ Passed

Notice Exhaust damaged**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #14**

2015-04-18 09:33

MOT test number

249498005168

Result

✗ Failed

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust damaged**MOT #13**

2014-04-19 12:40

MOT test number

349499504199

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12**

2014-04-19 11:24

MOT test number

935579304104

Result

✗ Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #11** 2013-04-20 12:21**MOT test number** 287550613498**Result** ✓ Passed**MOT #10** 2013-04-20 10:55**MOT test number** 785360413108**Result** ✗ Failed**Fail** Offside Front constant velocity joint is insecure (2.5.C.1b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #9** 2012-04-14 14:28**MOT test number** 937065002143**Result** ✓ Passed**MOT #8** 2012-04-14 11:03**MOT test number** 576935702178**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #7** 2011-03-26 11:05**MOT test number** 128895481497**Result** ✓ Passed**MOT #6** 2010-04-12 12:09**MOT test number** 883552000115**Result** ✓ Passed



MOT #5 2009-04-18 10:29

MOT test number 380178609170

Result ✓ Passed

Notice N/s/r tyre on legal limit

Notice Front registration marked

MOT #4 2008-04-07 12:35

MOT test number 730598398075

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #3 2007-04-13 16:43

MOT test number 803653707144

Result ✓ Passed



MOT #22007-04-12 14:56

MOT test number720032507118

ResultX Failed

- Fail

Offside Rear rear brake binding (3.7.B.1)
- Notice

BOTH REAR SHOCKER SLEEVES INSECURE
- Advice

Nearside Rear brake disc slightly scored (3.5.1h)
- Fail

Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Notice

Child seat fitted not allowing full inspection of adult belt
- Fail

Rear rear brake binding (3.7.B.1)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Fail

Offside Rear brake disc excessively pitted (3.5.1h)
- Notice

Nail in offside rear tyre

MOT #12006-04-06 12:43

MOT test number373166596020

Result✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-03-06
Last registration	2022-05-05
Complete history	See info



Registration #1	2003-03-06	25 mi
Registration #2	2006-04-06	26.171 mi
Registration #3	2007-04-13	33.928 mi
Registration #4	2008-04-07	38.375 mi
Registration #5	2009-04-18	41.865 mi
Registration #6	2010-04-12	44.590 mi
Registration #7	2011-03-26	46.831 mi
Registration #8	2012-04-14	50.217 mi
Registration #9	2012-04-14	50.219 mi
Registration #10	2013-04-20	53.183 mi
Registration #11	2013-04-20	53.186 mi
Registration #12	2014-04-19	56.367 mi
Registration #13	2014-04-19	56.368 mi
Registration #14	2015-05-20	59.557 mi
Registration #15	2015-05-20	59.557 mi
Registration #16	2015-05-20	59.557 mi
Registration #17	2015-05-20	59.557 mi
Registration #18	2015-05-20	59.557 mi
Registration #19	2015-05-20	59.557 mi
Registration #20	2015-05-20	59.557 mi
Registration #21	2015-05-20	59.557 mi
Registration #22	2015-05-20	59.557 mi
Registration #23	2015-05-20	59.557 mi
Registration #24	2015-05-20	59.557 mi
Registration #25	2015-05-20	59.557 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1196 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	FD260552373