




report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS EGS GRAND PICASSO
Colour	Brown
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-11
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-10-21
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	30
Total items failed	8

MOT #13	2021-10-12 09:59
MOT test number	944606269992
Result	✓ Passed
Next expiry date	2022-10-21

MOT #12	2021-10-12 09:59
MOT test number	478598792630
Result	✗ Failed
Pass with rectification	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot clip insecurely attached (6.1.7 (g) (ii))
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #11	2020-10-22 09:59
MOT test number	328364166537
Result	✓ Passed

**MOT #10**

2019-10-14 10:07

MOT test number

380880904912

Result

✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9

2018-10-18 10:03

MOT test number

844653996675

Result

✓ Passed

MOT #8

2018-10-18 10:03

MOT test number

916895222271

Result

✗ Failed

- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #7	2017-10-17 08:54
MOT test number	623703713963
Result	✓ Passed

MOT #6	2016-10-18 09:05
MOT test number	760068002818
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit 2.8mm (4.1.E.1)

MOT #5	2015-10-14 13:45
MOT test number	582842634259
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Rear seats folded down
Advice	Both rear tyres cracking badly
Advice	Nearside Rear Tyre worn close to the legal limit 1.6mm (4.1.E.1)
Advice	Undertrays fitted

**MOT #4**

2015-10-14 10:12

MOT test number

902346920586

Result**✗ Failed****Advice**

Undertrays fitted

Fail

Offside Front position lamp(s) not working (1.1.A.3b)

Advice

Nearside Rear Tyre worn close to the legal limit 1.6mm (4.1.E.1)

Advice

Rear seats folded down

Advice

Both rear tyres cracking badly

Fail

Nearside Front position lamp(s) not working (1.1.A.3b)

Advice

Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #3

2014-10-14 12:45

MOT test number

879617884280

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Under-trays fitted obscuring some underside components

MOT #2

2013-10-22 11:17

MOT test number

389495993298

Result**✓ Passed****Notice**

Engine covers fitted obscuring some components in the engine bay

Notice

Under-trays fitted obscuring some underside components



MOT #1	2013-10-22 11:17
MOT test number	936725193254
Result	✗ Failed
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

X

Untaxed

Tax expired:
24 March 2022

X

MOT

Expired:
21 October 2022

Tax status	Expired at 24 March 2022
Days left	768 days too late
MOT expiry date	21 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-14
Last registration	2021-10-12
Complete history	See info



Registration #1	2010-12-14	13 mi
Registration #2	2013-10-22	36.720 mi
Registration #3	2014-10-14	44.033 mi
Registration #4	2015-10-14	50.928 mi
Registration #5	2015-10-14	50.928 mi
Registration #6	2016-10-18	56.804 mi
Registration #7	2017-10-17	64.210 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2021-10-12	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1520 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCJ3026307