





report date: 2024-03-29

General information

| Make | VOLVO |
|---------------------|-----------------|
| Model | V40 T2 R-DESIGN |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 118 mph |
| 0 - 60 mph | 9.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 120 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 1.100 rpm |
| Engine capacity | 1.969 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 51.4 mpg |
| CO2 emission | 127 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 5

Date 2021-09-03

Pictures 44

Listing price <u>View report</u>









source: heycar.co.uk


Entry 4

Date 2021-09-02

Pictures 44

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date 2021-07-02

Pictures 4

Listing price <u>View report</u>





0





source: heycar.co.uk

Entry 2

Date 2021-06-26

Pictures CarCheck.co.uk

| Listing price | View report |
|------------------------|-------------|
| source: cargurus.co.uk | |
| Entry 1 | |
| Date | 2021-06-25 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



report date: 2024-03-29

MOT history

| MOT expiry date | 2025-02-16 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 0 |

| MOT #5 | | 2024-02-05 14:44 |
|---|--|------------------|
| MOT test | number | 655578248499 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-02-16 |
| Advice Rear Tyre slightly damaged both tyres wearing & out of shape inner treads (5.2.3 (d) (ii)) | | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #4 | | 2024-02-05 08:40 |
|-----------------------|---|--------------------|
| MOT test | number | 601448699621 |
| Result | | X Failed |
| Advice | Front Brake pad(s) wearing thin on minimum thickness (1.1.13 (a) (ii)) | |
| Advice sidewall (5 | Nearside Front Tyre worn close to legal limit/worn on edge very worn inner edg 5.2.3 (e)) | je, cut on outer |
| Advice | Brake fluid level slightly low | |
| Advice | Advice Rear Tyre slightly damaged both tyres wearing & out of shape inner treads (5.2.3 (d) (ii)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| DANGER | Offside Front Tyre has ply or cords exposed very worn / cords inner edge | e (5.2.3 (d) (ii)) |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2023-02-15 10:00

MOT test number 702687437044

Result ✓ Passed

Advice Front both tyres wearing inner edges

Advice Rear Tyre slightly damaged both tyres losing shape inner treads (5.2.3 (d) (ii))

Advice Offside Front brake lag - 20%

MOT #2 2022-02-10 08:59

MOT test number 910959845945

Result ✓ Passed

MOT #1 2021-02-17 10:02

MOT test number 208704894381

CarCheck.co.uk page 4/11



CX18NWH report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 16 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r | |
|---|-------------|
| | |
| | |
| | |
| *************************************** | |
| ******* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | OK OK |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



CX18NWH report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2018-03-26 |
| Last registration | 2024-02-05 |
| Complete history | See info |



| Registration #1 | 2018-03-26 | 7 mi |
|------------------|------------|-----------|
| Registration #2 | 2021-02-17 | 18.307 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 0.00 44 |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 44 |
| Registration #11 | | 11.777 mi |

More info >

CarCheck.co.uk page 10/11



CX18NWH report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 98% |
| Children | 75% |
| Pedestrian | 88% |
| Safety systems | 100% |
| Overall rating | 92% |
| Video | see crash video |



Dimensions & weight

| Width | 1857 mm |
|---------------------|---------|
| Height | 1439 mm |
| Length | 4369 mm |
| Wheel base | 2647 mm |
| Kerb weight | 1417 kg |
| Max. allowed weight | 1965 kg |

Additional information

| Fuel tank capacity | 62 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |

Number of axles2Engine number2348614