





report date: 2024-03-29

#### General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	115 BHP
Max. torque	172 Nm at 3.200 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	23.5 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K



CarCheck.co.uk page 1/14



# Internet history

#### Entry 1

Date 2021-10-03

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-10-06
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	24
Total items failed	5

MOT #21		2023-10-05 14:03
MOT test	number	497112372633
Result		✓ Passed
Next expiry date 2024-10-0		2024-10-06
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #20		2022-09-30 13:12
MOT test	number	104778441994
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #19	21	021-10-07 17:07
MOT test	number	123555611328
Result		✓ Passed
Advice	Driver seat buckle cover missing	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/14



✓ Passed

**MOT #18** 2021-10-07 09:47

**MOT test number** 930674196618

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Direction indicator incorrect colour (4.4.3 (a))

**Advice** Driver seat buckle cover missing

**MOT #17** 2021-04-10 10:56

MOT test number 695910335928

Result \sqrt{Passed}

**Advice** Front Coil spring corroded (5.3.1 (b) (i))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Central Exhaust mounting defective Bracket Corroded Through (Still Secure) (6.1.2 (a))

**Advice** Offside Front Play in steering rack inner joint(s)

**Advice** Offside Front Seat belt flexible stalk damaged (7.1.2 (b) (i))

**Advice** Rear Coil spring corroded (5.3.1 (b) (i))

Result

MOT #16 2020-04-07 15:36

**MOT test number** 341711687635

317/1100/033

**Advice** Offside Front Play in steering rack inner joint(s)

CarCheck.co.uk page 4/14



MOT #15

MOT test number

322461481744

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

MOT test number

653636426632

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #13
 2018-04-11 10:37

 MOT test number
 411099678061

 Result
 ✓ Passed

 MOT #12
 2017-04-12 10:00

 MOT test number
 133314683945

 Result
 ✓ Passed

MOT #11 2016-04-14 08:46

MOT test number 431433529976

Result ✓ Passed

 MOT #10
 2015-04-13 10:55

 MOT test number
 775343505195

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



MOT #9

LW04YXP report date: 2024-03-29

2014-04-14 10:00

MOT test number 609544104168

**Result** ✓ Passed

MOT #8 2013-04-09 12:42

**MOT test number** 457699693013

**Result** ✓ Passed

MOT #7 2012-04-05 11:14

**MOT test number** 357046492037

**Result** 
✓ Passed

MOT #6 2011-04-15 13:49

**MOT test number** 965055401199

MOT #5 2011-04-15 13:49

**MOT test number** 399035601169

Result × Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Pass with rectification** Offside Headlamp aim too high (1.8)

MOT #4 2009-12-19 11:26

**MOT test number** 862453459334

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 6/14



MOT #3 2009-05-13 12:58

**MOT test number** 931193339164

**Result** ✓ Passed

Advice

Offside Front Macpherson strut has slight movement in the upper support bearing assembly

(2.5.B.1b)

Notice Nearside and offside wiper blades starting to split

Advice

Nearside Front Macpherson strut has slight movement in the upper support bearing assembly

(2.5.B.1b)

**MOT #2** 2008-05-16 11:47

MOT test number 154867638103

Result 

Passed

**Notice** Nearside front tyre low tread

MOT #1 2007-05-14 09:59

**MOT test number** 263384737452

CarCheck.co.uk page 7/14



#### Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	6 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



LW04YXP


report date: 2024-03-29

#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Category

**Type** 

#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



LW04YXP

report date: 2024-03-29

# Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates -More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-05-26
Last registration	2023-10-05
Complete history	See info



Registration #1	2004-05-26	9 mi
Registration #2	2007-05-14	18.872 mi
Registration #3	2008-05-16	24.563 mi
Registration #4	2009-05-13	30.024 mi
Registration #5	2009-12-19	30.674 mi
Registration #6	2011-04-15	39.712 mi
Registration #7	2012-04-05	42.903 mi
Registration #8	2013-04-09	47.012 mi
Registration #9	2014-04-14	51.604 mi
Registration #10	2015-04-13	56.279 mi
Registration #11	2016-04-14	60.700 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.177 mi
Registration #16		11.777 es
Registration #17		11.177 mi
Registration #18		11.117 es
Registration #19		11.177 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		0.00 44

More info >

CarCheck.co.uk page 13/14



#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1770 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	3

CarCheck.co.uk page 14/14

Number of axles	2

Engine number AZJ725872