



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	JETTA SE TDI
Colour	Silver
Year of manufacture	2009
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-30
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-05-16
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	33
Total items failed	14

MOT #12 2021-05-17 12:12

MOT test number 587975876730

Result ✓ Passed

Next expiry date 2022-05-16

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Electronic stability control warning lamp not working (7.12 (e))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #11**

2021-05-14 08:34

**MOT test number**

152177573811

**Result****✗ Failed**

- Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Electronic stability control warning lamp not working (7.12 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Anti-lock braking system warning lamp does not illuminate (1.6 (a))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice** Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

**MOT #10**

2020-05-16 10:42

**MOT test number**

113492608635

**Result****✓ Passed**

**MOT #9** 2020-05-15 13:19**MOT test number** 889250077644**Result** ✗ Failed

- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #8** 2018-02-19 14:37**MOT test number** 495757066627**Result** ✓ Passed**MOT #7** 2018-02-13 15:02**MOT test number** 358318850548**Result** ✗ Failed

- Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)

**MOT #6** 2016-01-19 12:24**MOT test number** 492294674812**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (3.5.1i)
- Advice** Child seat fitted

**MOT #5** 2015-03-30 08:41**MOT test number** 739659885008**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Items removed from driver's view prior to test**Notice** Under-trays fitted obscuring some underside components**Notice** Tow ball/hitch not fitted at time of test**Notice** Vehicle's internal headlight adjuster altered to recheck lights**MOT #4** 2014-03-27 10:59**MOT test number** 329716784094**Result** ✓ Passed**MOT #3** 2013-03-15 15:43**MOT test number** 478984873040**Result** ✓ Passed**Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)**MOT #2** 2013-03-15 15:43**MOT test number** 328344173032**Result** ✗ Failed**Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #1** 2012-03-14 14:11**MOT test number** 565004972037**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
31 March 2022

X

MOT

Expired:  
16 May 2022

Tax status	Expired at 31 March 2022
Days left	759 days too late
MOT expiry date	16 May 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>WJ09RWU</b>
Plate since	2019-09-29
Current registration	 <b>WJ09RWU</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-03-16
Last registration	2021-05-17
Complete history	<a href="#">See info</a>



Registration #1	2009-03-16	29 mi
Registration #2	2012-03-14	81.135 mi
Registration #3	2013-03-15	121.397 mi
Registration #4	2014-03-27	129.906 mi
Registration #5	2015-03-30	135.498 mi
Registration #6	2016-01-19	141.112 mi
Registration #7	2018-02-13	248.376 mi
Registration #8	2019-05-20	251.277 mi
Registration #9	2020-05-20	251.277 mi
Registration #10	2020-05-20	251.277 mi
Registration #11	2020-05-20	251.277 mi
Registration #12	2020-05-20	251.277 mi
Registration #13	2021-05-17	251.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1508 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BXEB69305