



report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER S ALL4 COOPER S ALL4
Colour	Red
Year of manufacture	-
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-06
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #15	2023-11-22 11:43
MOT test number	583641464108
Result	✓ Passed
Next expiry date	2024-11-21
Advice	Offside Front Brake disc worn, but not excessively liped (1.1.14 (a) (i))
Advice	Nearside Front Brake disc worn, but not excessively liped (1.1.14 (a) (i))

MOT #14	2022-09-16 12:11
MOT test number	164223137481
Result	✓ Passed

MOT #13	2021-09-13 14:39
MOT test number	973161670547
Result	✓ Passed

MOT #12	2021-05-10 11:45
MOT test number	219621856268
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2021-05-07 10:10
MOT test number	784269250289
Result	✗ Failed
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Brake fluid significantly below minimum mark (1.1.10 (d) (ii))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #10** 2020-01-27 15:20**MOT test number** 473597073410**Result** ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9 2019-12-24 12:33**MOT test number** 985980278446**Result** ✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Nearside Rear Stop lamp(s) emits other than a steady red light (4.3.3 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #8 2018-07-17 16:29**MOT test number** 365111292387**Result** ✓ Passed

Advice Tyre worn close to legal limit/worn on edge both rear close to cords on inner edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2018-07-11 14:27**MOT test number** 834477512083**Result** ✗ Failed

Advice Tyre worn close to legal limit/worn on edge both rear close to cords on inner edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

**MOT #6** 2017-07-04 14:50**MOT test number** 917589003804**Result** ✓ Passed**Advice** N/s/f tyre worn on inner edge close to cords**MOT #5** 2016-06-20 14:34**MOT test number** 895004163211**Result** ✓ Passed**MOT #4** 2016-03-09 13:09**MOT test number** 834557089540**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2015-07-28 17:02**MOT test number** 938139205208**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #2** 2015-07-27 11:45**MOT test number** 757768005218**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** O/s/r tyre wearing on inner edge and nail in tread**Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #1	2015-03-18 11:32
MOT test number	706087175083
Result	✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-03-28
Last registration	2023-11-22
Complete history	See info



Registration #1	2012-03-28	14 mi
Registration #2	2015-03-18	18.187 mi
Registration #3	2015-07-27	20.208 mi
Registration #4	2015-07-28	20.208 mi
Registration #5	2016-03-09	21.458 mi
Registration #6	2016-06-20	21.839 mi
Registration #7	2017-07-04	32.423 mi
Registration #8	2018-07-11	43.889 mi
Registration #9	2018-07-17	44.008 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1380 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A773J079