





report date: 2024-03-28

General information

Make	PEUGEOT
Model	508 HDI SW ACTIVE NAVIGATION VERSION
Colour	White
Year of manufacture	2014
Top speed	139 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-07-04	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-07-03
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	0

MOT #11	2023-06-30 12:51
MOT test number	668658111846
Result	✓ Passed
Next expiry date	2024-07-03

MOT #10	2023-06-30 08:37
MOT test number	er 514604541628
Result	★ Failed
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
DANGEROUS (d) (ii))	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3

MOT #9	2022-07-04 14:06
MOT test number	700200552708
Result	✓ Passed
Advice Offside rear tyre wearing inner edge	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2022-07-04 09:10

MOT test number 991447165989

Result X Failed

DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside rear tyre wearing inner edge

MOT #7 2021-07-02 14:27

MOT test number 781461763092

Result ✓ Passed

MOT #6 2021-07-01 12:23

MOT test number 586356181689

Result X Failed

DANGEROUS Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #5 2021-06-14 09:26

MOT test number 780850701804

Result / Passed

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2020-06-25 09:23

MOT test number 314500696439

Result

Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

2019-06-24 09:50 **MOT** #3 319396801286 **MOT test number** Result ✓ Passed **Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt **Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2		2018-07-02 11:56
MOT test	number	413943562072
Result		✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #1	2017-05-16 09:09
MOT test number	270446937101
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	3 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	history
OWITCH	THISCOLY

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

THE STREET STREE	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-17
Last registration	2023-06-30
Complete history	See info



Registration #1	2014-01-17	29 mi
Registration #2	2017-05-16	47.011 mi
Registration #3	2018-07-02	58.875 mi
Registration #4	2019-06-24	66.377 mi
Registration #5	2020-06-25	75.488 mi
Registration #6	2021-06-14	83.947 mi
Registration #7	2021-07-01	84.133 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1853 mm
Height	1476 mm
Length	4813 mm
Wheel base	2817 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

		•
Fuel tank capacity	72 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number DYZD4060617