





## General information

Make	FIAT
Model	500C TWINAIR C LOUNGE DUALOGIC
Colour	White
Year of manufacture	2013
Top speed	107 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	90 g/km
CO2 label	А








# Internet history

Entry 2	
Date	2021-08-07
Pictures	29
Listing price	View report









source: autotrader.co.uk

## Entry 1

Date

Pictures

Listing price

2021-07-27 11

View report



source: autotrader.co.uk







## MOT history

MOT expiry date	2024-11-09
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	3

MOT #12	2023-11-10 15:03
MOT test number	829654550297
Result	✓ Passed
Next expiry date	2024-11-09
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

#### MOT #11 2023-11-10 15:03 **MOT test number** 724475461790 Result × Failed Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Pass with rectification Rear Direction indicator incorrect colour both (4.4.3 (a)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



RX13M	W	Μ
report date:	2024-	03-29

MOT #10		2022-10-31 11:49
MOT test	number	591525181827
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Front Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))	
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.	3 (d) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #9		2022-:	10-31 11:49
MOT test	number	288	765149343
Result			🗙 Failed
Pass wit	h rectification	Offside Front Side repeater not working (4.4.1 (a) (ii))	
Advice	Front Tyre slight	ly damaged/cracking or perishing Both (5.2.3 (d) (ii))	
Advice	Vice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))			
Advice	Offside Front Ty	re has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Nearside Rear D	irection indicator slightly discoloured (4.4.3 (a))	

MOT #8	2021-09-13 15:55
MOT test number	440242468394
Result	✓ Passed

MOT #7	2020-10-21 10:46
MOT test number	626860351779
Result	✓ Passed





MOT #6		2020-10-21 10:46
MOT test number		331547487367
Result		🗙 Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))	
MOT #5		2019-10-25 10:51
MOT test number		918999160992
Result		🗸 Passed
MOT #4		2018-10-24 08:20
MOT test number		267982288260
Result		✓ Passed
MOT #3		2018-05-25 10:44
MOT test number		907342194515
Result		✓ Passed
NOT #2		
MOT #2 MOT test number		2017-05-26 10:06 394120290110
Result		✓ Passed
Advice Cut to nearside	rear tyre outer sidewall, but not showing canvas	
MOT #1		2016-05-27 11:06
MOT #1		431377857106
		431311631100

Result

🗸 Passed



**RX13MWM** report date: 2024-03-29

# Tax & MOT check

√ Taxed	√ мот	
Tax due: 1 November 2024	<b>Expires:</b> 9 November 2024	
Tax status	Valid until 1 November	
Days left	186	
MOT expiry date	9 November 2024	
Full MOT history	See MOT history	
Tax calculation		

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





## Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





# Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-05-31
Last registration	2023-11-10
Complete history	See info



Registration #1	2013-05-31	19 mi
Registration #2	2016-05-27	11.694 mi
Registration #3	2017-05-26	14.663 mi
Registration #4	2018-05-25	17.026 mi
Registration #5	2018-10-24	18.082 mi
Registration #6	2019-10-25	18.202 mi
Registration #7	2020-10-21	19.382 mi
Registration #8	2020-10-21	19.382 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi
Registration #12		11.777 mi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi





## Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1395 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	0194696