



report date: 2024-03-29

General information

Make	BMW
Model	525 525I SPORT
Colour	Black
Year of manufacture	2003
Top speed	144 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	189 BHP
Max. torque	245 Nm at 3.500 rpm
Engine capacity	2.494 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.6 mpg
Consumption extra urban	35.8 mpg
Consumption combined	27.4 mpg
CO2 emission	247 g/km
CO2 label	L





## MOT history

MOT expiry date	2021-07-01
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	33
Total items failed	18

MOT #18 2020-07-02 17:34

MOT test number 495775424175

Result ✓ Passed

Next expiry date 2021-07-01

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #17 2020-07-02 17:34

MOT test number 250670885221

Result ✗ Failed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Pass with rectification** Front All direction indicators not working both side (4.4.1 (a) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Stop lamp(s) not working both side (4.3.1 (a) (ii))

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))



MOT #162019-05-02 09:14

MOT test number193964786319

Result

✓ Passed

- Advice

Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice

Oil leak
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2019-04-26 13:01

**MOT test number**

604550002251

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Oil leak
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #14**

2013-12-31 14:49

**MOT test number**

528995463333

**Result****✓ Passed**

- Notice** Oil leak

**MOT #13** 2013-12-31 14:49**MOT test number** 116915263329**Result** ✗ Failed**Notice** Oil leak**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #12** 2012-12-28 09:40**MOT test number** 548603762397**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2012-12-28 09:40**MOT test number** 596673062392**Result** ✗ Failed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #10** 2011-12-29 17:43**MOT test number** 865273761364**Result** ✓ Passed**Notice** Front brake discs worn

**MOT #9** 2011-12-29 17:06**MOT test number** 775993761381**Result** ✗ Failed

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Notice** Front brake discs worn

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #8** 2010-12-23 17:26**MOT test number** 584137350345**Result** ✓ Passed

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2010-12-23 16:50**MOT test number** 330047050321**Result** ✗ Failed

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2009-12-29 14:15**MOT test number** 492563869433**Result** ✓ Passed

**MOT #5** 2009-12-29 13:42**MOT test number** 700473369313**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2008-12-06 13:36**MOT test number** 914541648372**Result** ✓ Passed**Notice** Offside front tyre worn outer edge**MOT #3** 2007-11-30 15:55**MOT test number** 952994737342**Result** ✓ Passed**MOT #2** 2007-11-30 14:56**MOT test number** 310914137366**Result** ✗ Failed**Fail** Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #1** 2006-08-23 15:27**MOT test number** 384585636262**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
28 February 2021

✕  
MOT

Expired:  
1 July 2021

Tax status	Expired at 28 February 2021
Days left	1157 days too late
MOT expiry date	1 July 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2003-09-29
Last registration	2020-07-02
Complete history	<a href="#">See info</a>



Registration #1	2003-09-29	11 mi
Registration #2	2006-08-23	42.963 mi
Registration #3	2007-11-30	58.174 mi
Registration #4	2007-11-30	58.174 mi
Registration #5	2008-12-06	69.838 mi
Registration #6	2009-12-29	77.401 mi
Registration #7	2009-12-29	77.402 mi
Registration #8	2010-12-23	82.319 mi
Registration #9	2010-12-23	82.319 mi
Registration #10	2010-12-23	82.319 mi
Registration #11	2010-12-23	82.319 mi
Registration #12	2010-12-23	82.319 mi
Registration #13	2010-12-23	82.319 mi
Registration #14	2010-12-23	82.319 mi
Registration #15	2010-12-23	82.319 mi
Registration #16	2010-12-23	82.319 mi
Registration #17	2010-12-23	82.319 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1800 mm
Height	1435 mm
Length	4775 mm
Wheel base	1558 mm

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	33002991