



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI (130BHP) TIPTRONIC
Colour	Green
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-05
Pictures	25
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #27** 2022-09-14 12:52**MOT test number** 712367749363**Result** ✓ Passed**Next expiry date** 2023-09-14

- Advice** Rear Passenger seat(s) missing at time of test
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #26 2022-09-14 12:52**MOT test number** 614862771518**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Rear Passenger seat(s) missing at time of test
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #25**

2021-09-15 15:03

MOT test number

612361696543

Result

✓ Passed

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #24

2020-10-30 15:26

MOT test number

273183745316

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #23

2020-10-27 11:23

MOT test number

243445520067

Result

✗ Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

Fail Nearside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #22**

2019-04-27 11:04

MOT test number

785874348091

Result

✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Upper Suspension arm ball joint has slight play inner (5.3.4 (a) (i))

MOT #21

2019-04-25 08:08

MOT test number

430036214544

Result

✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear arm (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #20**

2018-04-25 09:56

MOT test number

614184805287

Result

✓ Passed

- Advice** Both front upper front and rear suspension arm inner bushes worn
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin bearing c link (2.4.G.2)
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint c link (2.4.G.2)

MOT #19

2018-04-24 10:46

MOT test number

895986570506

Result

✗ Failed

- Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint c link (2.4.G.2)
- Advice** Both front upper front and rear suspension arm inner bushes worn
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin bearing c link (2.4.G.2)

**MOT #18** 2017-04-12 15:41**MOT test number** 245266596739**Result** ✓ Passed**Advice** Offside Front Upper rear suspension arm inner bush worn**Advice** Oil leak**Advice** Both anti roll bar c links worn**MOT #17** 2017-04-12 08:54**MOT test number** 863796430039**Result** ✗ Failed**Advice** Oil leak**Advice** Offside Front Upper rear suspension arm inner bush worn**Fail** Brake pedal has no servo assistance (3.3.B.2)**Advice** Both anti roll bar c links worn**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #16** 2016-04-21 15:03**MOT test number** 785647492437**Result** ✓ Passed**Advice** Childrens seats fitted in vehicle**MOT #15** 2016-04-20 16:08**MOT test number** 387094233867**Result** ✗ Failed**Advice** Childrens seats fitted in vehicle**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #14** 2015-04-17 10:05**MOT test number** 529877205197**Result** ✓ Passed**MOT #13** 2015-04-16 15:51**MOT test number** 845486305188**Result** ✗ Failed**Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**MOT #12** 2014-04-14 09:55**MOT test number** 635374904119**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Notice** O/s front and n/s rear tyres wearing low inner edges[suggest o/s front replaced soon]**Notice** Rear brake pads bit low**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Both headlights bit dim and poor patterns**Notice** Oil leak**MOT #11** 2013-04-27 08:49**MOT test number** 675757013160**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Notice** Oil leak**Notice** B oth headlights bit dim,o/s front tyre wearing bit low inner edge

**MOT #10**

2013-04-25 09:27

MOT test number

256455613124

Result

✗ Failed

Notice Items removed from driver's view prior to test**Fail** Nearside Stop lamp not working (1.2.1b)**Notice** Oil leak**Notice** B oth headlights bit dim,o/s front tyre wearing bit low inner edge**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #9**

2012-04-27 08:14

MOT test number

956328712100

Result

✓ Passed

Notice Oil leak**Advice** Brake hose slightly deteriorated (3.6.B.4d)**Notice** Items removed from driver's view prior to test**MOT #8**

2012-04-26 10:10

MOT test number

609787612163

Result

✗ Failed

Notice Oil leak**Advice** Brake hose slightly deteriorated (3.6.B.4d)**Notice** Items removed from driver's view prior to test**Fail** Offside Stop lamp not working (1.2.1b)**MOT #7**

2011-04-27 18:52

MOT test number

259737611494

Result

✓ Passed



MOT #6	2010-03-22 12:34
---------------	------------------

MOT test number	140791580445
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2009-03-30 15:52
---------------	------------------

MOT test number	821019589074
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2008-04-08 12:37
---------------	------------------

MOT test number	800059398077
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2007-03-26 16:08
---------------	------------------

MOT test number	414285587033
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2006-03-22 11:41
---------------	------------------

MOT test number	420051986045
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2006-03-22 11:41
---------------	------------------

MOT test number	870091886014
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
--------------------------------	---

Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
--------------------------------	--

Pass with rectification	Nearside Headlamp aim too low when the centre of the headlamp is below 850mm from the ground (1.6.B2)
--------------------------------	---



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GK02VAA
Plate since	2020-03-28
Current registration	 GK02VAA
Plate since	2020-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-04-06
Last registration	2022-09-14
Complete history	See info



Registration #1	2002-04-06	24 mi
Registration #2	2006-03-22	42.444 mi
Registration #3	2007-03-26	48.825 mi
Registration #4	2008-04-08	54.931 mi
Registration #5	2009-03-30	58.951 mi
Registration #6	2010-03-22	64.198 mi
Registration #7	2011-04-27	71.008 mi
Registration #8	2012-04-26	83.398 mi
Registration #9	2012-04-27	83.398 mi
Registration #10	2013-04-25	94.004 mi
Registration #11	2013-04-27	94.004 mi
Registration #12	2014-04-14	100.040 mi
Registration #13	2015-04-16	105.720 mi
Registration #14	2015-04-17	105.720 mi
Registration #15	2016-04-14	111.760 mi
Registration #16	2016-04-15	111.760 mi
Registration #17	2016-04-16	111.760 mi
Registration #18	2016-04-17	111.760 mi
Registration #19	2016-04-18	111.760 mi
Registration #20	2016-04-19	111.760 mi
Registration #21	2016-04-20	111.760 mi
Registration #22	2016-04-21	111.760 mi
Registration #23	2016-04-22	111.760 mi
Registration #24	2016-04-23	111.760 mi
Registration #25	2016-04-24	111.760 mi
Registration #26	2016-04-25	111.760 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1498 mm
Length	4682 mm
Wheel base	2703 mm
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number

AVF151161