



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 GLX
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-20
Pictures	10
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #22** 2022-10-14 17:49**MOT test number** 965697544078**Result** ✓ Passed**Next expiry date** 2023-10-13

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

MOT #21 2021-09-08 11:28**MOT test number** 503067772559**Result** ✓ Passed

- Advice** All front and rear hub components corroded
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides corroded (1.1.14 (a) (ii))
- Advice** Nearside Front Windscreen washer: jet not working
- Advice** Tyre slightly damaged/cracking or perishing all 4 tyres front and rear (5.2.3 (d) (ii))

**MOT #20**

2021-09-07 13:38

MOT test number

114995677728

Result**✗ Failed**

- Advice** All front and rear hub components corroded
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides corroded (1.1.14 (a) (ii))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Front Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))
- Advice** Nearside Front Windscreen washer: jet not working
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Tyre slightly damaged/cracking or perishing all 4 tyres front and rear (5.2.3 (d) (ii))

MOT #19

2020-08-03 15:47

MOT test number

834165616570

Result**✓ Passed**

- Advice** Offside Rear Nail in tyre
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Tyre slightly damaged/cracking or perishing all 4 (5.2.3 (d) (ii))

MOT #18

2019-04-26 13:10

MOT test number

499026944326

Result**✓ Passed**

**MOT #17** 2019-04-26 07:56**MOT test number** 645862116144**Result** ✗ Failed

- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #16 2018-04-25 09:36**MOT test number** 161809731130**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #15 2018-04-24 09:17**MOT test number** 134075548924**Result** ✗ Failed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)

MOT #14 2017-04-25 11:12**MOT test number** 757137798604**Result** ✓ Passed**MOT #13** 2016-04-25 09:17**MOT test number** 319966584764**Result** ✓ Passed

**MOT #12** 2015-04-17 09:47**MOT test number** 228197805411**Result** ✓ Passed**Notice** O/s/r tyre has perishing cracks in tread**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Notice** N/s/f wing liner insecure**MOT #11** 2014-04-16 14:14**MOT test number** 635626304115**Result** ✓ Passed**MOT #10** 2014-04-16 11:59**MOT test number** 516346104185**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Side repeater incorrect colour (1.4.A.2f)**MOT #9** 2013-04-18 12:27**MOT test number** 278248103421**Result** ✓ Passed**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Notice** N/s/f tyre worn on outer edge and has perishing cracks**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2012-04-26 09:40**MOT test number** 409387012130**Result** ✓ Passed**Advice** Nearside Front Side repeater slightly discoloured (1.4.A.2f)**MOT #7** 2011-04-11 12:21**MOT test number** 818791001160**Result** ✓ Passed**MOT #6** 2011-04-11 10:19**MOT test number** 647261901176**Result** ✗ Failed**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Side repeater incorrect colour (1.4.A.2f)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Wheel stud(s) missing (4.2.A.1e)**MOT #5** 2010-04-20 10:25**MOT test number** 990250110122**Result** ✓ Passed**MOT #4** 2009-04-15 11:12**MOT test number** 802575409158**Result** ✓ Passed**MOT #3** 2008-04-24 09:41**MOT test number** 764895518131**Result** ✓ Passed



MOT #2	2007-03-30 15:04
MOT test number	860989687016
Result	✓ Passed
MOT #1	2006-04-07 15:52
MOT test number	910047296060
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-04-26
Last registration	2022-10-14
Complete history	See info



Registration #1	2002-04-26	26 mi
Registration #2	2006-04-07	24.485 mi
Registration #3	2007-03-30	30.198 mi
Registration #4	2008-04-24	37.615 mi
Registration #5	2009-04-15	44.372 mi
Registration #6	2010-04-20	48.723 mi
Registration #7	2011-04-11	51.563 mi
Registration #8	2011-04-11	51.565 mi
Registration #9	2012-04-26	55.838 mi
Registration #10	2013-04-18	58.285 mi
Registration #11	2014-04-16	60.864 mi
Registration #12	2014-04-16	60.869 mi
Registration #13	2015-04-16	63.317 mi
Registration #14	2015-04-16	63.317 mi
Registration #15	2015-04-16	63.317 mi
Registration #16	2015-04-16	63.317 mi
Registration #17	2015-04-16	63.317 mi
Registration #18	2015-04-16	63.317 mi
Registration #19	2015-04-16	63.317 mi
Registration #20	2015-04-16	63.317 mi
Registration #21	2015-04-16	63.317 mi
Registration #22	2015-04-16	63.317 mi
Registration #23	2015-04-16	63.317 mi
Registration #24	2015-04-16	63.317 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1990 mm
Height	1514 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1229 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	FX2F1635993