

Ford



General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С







Internet history

Entry 1

Date Pictures 2021-01-30

10

Listing price

View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-15
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	20
Total items failed	4

MOT #15	2023-05-16 14:08
MOT test number	819656215670
Result	✓ Passed
Next expiry date	2024-05-15

MOT #14	2023-05-16 13:15
MOT test number	626340068227
Result	🗙 Failed
Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	

MOT #13	2022-05-06 11:11
MOT test number	934718999669
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #12	2021-02-15 18:07
MOT test number	212438543480
Result	✓ Passed





MOT #11	2020-03-09 13:12
MOT test number	228846642248
Result	✓ Passed
MOT #10	2020-03-09 13:12
MOT test number	723059967949
Result	🗙 Failed

Pass with rectification Exhaust system insecure (6.1.2 (a))

MOT #9		2019-03-21 15:04
MOT test	number	904323128646
Result		✓ Passed
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effe	ct (5.3.2 (b))

MOT #8	2019-03-21 15:04	
MOT test number	274335702818	
Result	× Failed	
Pass with rectification (4.7.1 (b) (ii))	Registration plate lamp inoperative in the case of a single lamp or all lamps	
Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		

MOT #7	2018-03-20 16:22
MOT test number	727222523455
Result	✓ Passed

MOT #6		2017-03-20 14:41
MOT test	number	490090590480
Result		✓ Passed
Advice	Front Tyre worn close to the legal limit Both (4.1.E.1)	
Advice braking sy	Rear parking (secondary) brake imbalance requirements only just met. It would ystem requires adjustment or repair. (3.7.B.6b)	appear that the





MOT #5		2016-03-12 14:55
MOT test	number	509689780941
Result		✓ Passed
Advice	Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)	
Advice	Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	
Advice	Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)	
Advice	Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	

МОТ #4	2016-03-07 14:52
MOT test number	266947178165
Result	× Failed
Advice Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)	
Advice Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	
Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3)	
Advice Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)	
Advice Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)	

MOT #3	2015-03-20 16:43
MOT test number	105709775076
Result	✓ Passed





MOT #2	2014-03-20 10:57
MOT test number	397099374078
Result	✓ Passed
MOT #1	2013-03-22 10:13
MOT test number	879561083065
Result	✓ Passed
Notice Front tyres wearing on outer edges	
Notice Rear silencer deteriorated	



Tax & MOT check

✓ Taxed Tax due: 1 June 2024		✓ MOT Expires: 15 May 2024	
Tax status		Valid	until 1 June
Days left			32
MOT expiry date			15 May 2024
Full MOT history		See	MOT history
Tax calculation			
Vehicle class		48	

venicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In kilometers
Mileage registrations	17
First mileage registration	2010-03-04
Last registration	2023-05-16
Complete history	<u>See info</u>



Registration #1	2010-03-04	29 mi
Registration #2	2013-03-22	12.417 mi
Registration #3	2014-03-20	16.023 mi
Registration #4	2015-03-20	25.050 mi
Registration #5	2016-03-07	33.730 mi
Registration #6	2016-03-12	33.965 mi
Registration #7	2017-03-20	39.481 mi
Registration #8	2018-03-20	43.281 mi
Registration #9	2019-03-21	47.269 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	5775203