



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





## Internet history

### Entry 3


Date	2021-11-03
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date	2021-08-14
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2021-02-05
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-11-29
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	33
Total items failed	8

MOT #132023-11-29 09:15

MOT test number607623778316

Result✓ Passed

Next expiry date2024-11-29

- Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2023-11-28 12:21

**MOT test number**

631461143872

**Result****✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2022-11-30 16:37

**MOT test number**

614704212131

**Result****✓ Passed**

- Advice** Rear Tyre slightly damaged/cracking or perishing Both OS+NS deep cracks (5.2.3 (d) (ii))
- Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Advice** Offside Front Nail in tyre
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to back (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2022-11-29 14:35

**MOT test number**

951857713666

**Result****✗ Failed****Advice** Rear Tyre slightly damaged/cracking or perishing Both OS+NS deep cracks (5.2.3 (d) (ii))**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Advice** Offside Front Nail in tyre**Fail** Nearside Brake pipe excessively corroded Front to back (rear section) (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Brake pipe corroded, covered in grease or other material Front to back (1.1.11 (c))**MOT #9**

2021-11-25 16:51

**MOT test number**

836116724233

**Result****✓ Passed****Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #8**

2020-10-17 18:49

**MOT test number**

901013722069

**Result****✓ Passed****MOT #7**

2019-10-18 11:57

**MOT test number**

227786057293

**Result****✓ Passed****Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2019-10-17 08:01**MOT test number** 744323212888**Result** ✗ Failed**Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge badly worn on edges (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Reversing lamp inoperative (4.6.1 (a))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2018-10-17 08:50**MOT test number** 233585740762**Result** ✓ Passed**MOT #4** 2017-10-10 11:00**MOT test number** 666120113734**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit also has cracks on the inner sidewall (4.1.E.1)**Advice** Offside number plate light was inop but came back on for the duration of the test.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Heat shield on the rear silencer is loose**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-10-18 14:04**MOT test number** 496403094298**Result** ✓ Passed**Advice** Offside Rear tyre heavily perished but no cords exposed



MOT #2	2016-10-18 14:04
MOT test number	323994489517
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Offside Rear tyre heavily perished but no cords exposed

MOT #1	2015-11-13 11:09
MOT test number	944329395976
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
29 November 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	29 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>WP62DDF</b>
Plate since	2024-03-29
Current registration	<b>WP62DDF</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-01-11
Last registration	2023-11-29
Complete history	<a href="#">See info</a>



Registration #1	2013-01-11	26 mi
Registration #2	2015-11-13	27.010 mi
Registration #3	2016-10-18	31.959 mi
Registration #4	2016-10-18	31.959 mi
Registration #5	2017-10-10	44.111 mi
Registration #6	2018-10-17	58.301 mi
Registration #7	2019-10-17	69.759 mi
Registration #8	2019-10-18	69.762 mi
Registration #9	2020-10-17	77.537 mi
Registration #10	2020-10-17	77.537 mi
Registration #11	2020-10-17	77.537 mi
Registration #12	2020-10-17	77.537 mi
Registration #13	2020-10-17	77.537 mi
Registration #14	2020-10-17	77.537 mi
Registration #15	2020-10-17	77.537 mi
Registration #16	2020-10-17	77.537 mi
Registration #17	2020-10-17	77.537 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ