






report date: 2024-03-28

General information

Make	AUDI
Model	A2 TDI SE
Colour	Black
Year of manufacture	-
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	195 Nm at 2.200 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	80.7 mpg
Consumption combined	65.7 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-13

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT #20 2023-01-16 15:05

MOT test number 619505732134

Result ✓ Passed

Next expiry date 2024-01-23

Minor Front Headlamp lens slightly defective both (4.1.1 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

MOT #19 2022-01-24 15:55

MOT test number 585013681988

Result
✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Minor

Offside Front Tyre obviously under inflated (5.2.3 (I))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #17

MOT test number

Result

MOT #16

2019-07-15 09:24

450597144504

✓ Passed

MOT test number 172896090550

Result \(\sqrt{Passed} \)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #15 2018-05-09 12:09

MOT test number 388365148671

Result X Failed

Fail Nearside Rear coil spring broken (2.4.C.1a)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail Nearside front brake recording little or no effort (3.7.B.5a)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Rear tyre worn on inner edge

Fail Service brake: efficiency below requirements (3.7.B.7)

Fail Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Front Brakes imbalanced across an axle Axle 1 (3.7.B.5b)

Fail Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

Fail Brake pedal creeps down under servo assistance and touches the floor (3.3.C.3)

Fail Offside rear brake recording little or no effort Hand brake and foot brake (3.7.B.5a)

Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside main beam bulb fitted incorrectly

Fail Nearside Rear wheel cylinder leaking (3.6.A.1)

Fail Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #14 2017-05-12 08:17

MOT test number 852893137585

Result ✓ Passed

Advice Wet test

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Shock absorber has a slightly worn shock absorber pivot (2.7.4)

Advice Oil leak

Advice Offside Rear Shock absorber has a slightly worn shock absorber pivot (2.7.4)

MOT #13 2016-05-11 12:56

MOT test number 350951522235

Result

Passed

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

Advice Oil leak

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #12 2016-05-11 09:09 548754384491 **MOT** test number Result × Failed Fail Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f) **Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2) **Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a) Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f) Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the Advice ingress of dirt (2.4.G.2) Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a) Advice **Advice** Oil leak

MOT #11	2015-04-21 11:00
MOT test number	797391815116
Result	✓ Passed
MOT #10	2013-01-22 09:22
MOT test number	129942423475
Result	✓ Passed

MOT #9		2012-01-17 09:14
MOT test	number	477957312036
Result		✓ Passed
Notice	Offside front tyre tread weraring off inside edge	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nearside front tyre tread wearing off inside edge	

CarCheck.co.uk page 7/15



report date: 2024-03-28

✓ Passed

MOT #8 2011-01-29 08:54

MOT test number 927569521084

MOT #7 2011-01-29 08:54

MOT test number 267789921027

Result × Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

MOT #6 2010-01-23 10:19

MOT test number 733463620037

Result ✓ Passed

MOT #5 2009-01-19 12:13

MOT test number 572499119085

Result ✓ Passed

Notice Engine undertray fitted

Notice Outer sill covers fitted

MOT #4 2008-01-30 12:10

MOT test number 141100438400

111100 100 100

Notice 1) Front anti-roll bar bushes showing signs of wear.

Notice 2) N/S/R and O/S/R tyres close to legal limit (wearing on inner edge)also tyres are slightly

distorted.

Result

MOT #3 2007-02-14 15:47

MOT test number 744095547069

Result
✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

MOT #2	2007-02-14 15:30
MOT test number	414015447000
Result	× Failed
Fail Offside Rear Registration plate lamp insecure (1.1.C.1c)	

MOT #1	2006-04-19 12:12
MOT test number	102799706119
Result	✓ Passed

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J		ve?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



AU02ZGA report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2002-04-18
Last registration	2023-01-16
Complete history	See info



2002-04-18	12 mi
2006-04-19	31.977 mi
2007-02-14	34.847 mi
2007-02-14	34.847 mi
2008-01-30	51.236 mi
2009-01-19	71.023 mi
2010-01-23	90.696 mi
2011-01-29	108.567 mi
2012-01-17	121.808 mi
2013-01-22	135.923 mi
2015-04-21	154.870 mi
	11.777 es
	11.117 es
	11.777 es
	11.117 es
	11.777 es
	11.777 es
	71,777 au
	2006-04-19 2007-02-14 2007-02-14 2008-01-30 2009-01-19 2010-01-23 2011-01-29 2012-01-17 2013-01-22 2015-04-21

More info >

CarCheck.co.uk page 14/15



AU02ZGA report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1676 mm
Height	1550 mm
Length	3810 mm
Wheel base	2405 mm
Kerb weight	990 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	34 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of axles CarCheck.co.uk	2	page 15/15