





General information

| Make | KIA |
|---------------------|-------------------|
| Model | NIRO 3 |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 101 mph |
| 0 - 60 mph | 11.1 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption


| Power | 104 BHP |
|-------------------------|---------------------|
| Max. torque | 147 Nm at 4.000 rpm |
| Engine capacity | 1.580 cc |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 64.2 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 101 g/km |
| CO2 label | В |





Internet history

| Entry 3 | |
|---------------|-------------|
| Date | 2021-11-23 |
| Pictures | 10 |
| Listing price | View report |




source: autoonline.co.uk

~

| Entry 2 | |
|---------------|-------------|
| Date | 2021-10-26 |
| Pictures | 0 |
| Listing price | View report |
| | |

source: heycar.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-10-05 |
| Pictures | 16 |
| Listing price | View report |



source: autotrader.co.uk









MOT history

| MOT expiry date | 2025-02-27 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 2 |

| MOT #6 | | 2024-02-28 16:20 |
|-----------|---|------------------|
| MOT test | number | 312908787904 |
| Result | | Passed |
| Next expi | ry date | 2025-02-27 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge Worn on edge. (5.2.3 | (e)) |
| Advice | Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge Worn on edge. (5.2 | .3 (e)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (| 1.1.14 (a) (ii)) |





| MOT #5 | 2024-02-28 09:32 |
|---|-----------------------|
| MOT test number | 740201181620 |
| Result | 🗙 Failed |
| Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened | ed (1.1.14 (a) (ii)) |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn on edge. | (5.2.3 (e)) |
| Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii) |)) |
| Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weaker | ned (1.1.14 (a) (ii)) |
| Fail Hazard warning switch inoperative (4.4.2 (a) (ii)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn on edge. (| 5.2.3 (e)) |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or co | rds (5.2.3 (d) (i)) |

| MOT #4 | 2024-01-05 11:02 |
|-----------------|------------------|
| MOT test number | 434055431896 |
| Result | ✓ Passed |
| | |
| МОТ #3 | 2022-11-15 16:36 |
| MOT test number | 830921160376 |
| Result | ✓ Passed |
| | |
| МОТ #2 | 2021-11-23 09:47 |
| MOT test number | 583322258756 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2021-03-01 13:19 |
| MOT test number | 102110496596 |

| MOT test number | IC |
|-----------------|----|
| Result | |

🗸 Passed



Tax & MOT check

| Taxed Tax due: 1 February 2025 | ✓ MOT Expires: 27 February 2025 |
|--------------------------------------|--|
| Tax status | Valid until 1 February |
| Days left | 279 |
| MOT expiry date | 27 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 59 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 175,00,- |
| Standard rate (12 months) | £ 170,00,- |
| Standard rate (6 months) | £ 93,50,- |
| Premium rate (12 months) | £ 560,00,- |
| Premium rate (6 months) | £ 308,00,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ******* | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| In miles |
|------------|
| 10 |
| 2018-03-01 |
| 2024-02-28 |
| See info |
| |



| Registration #1 | 2018-03-01 | 24 mi |
|------------------------------------|------------|--|
| Registration #2 | 2021-03-01 | 13.982 mi |
| Registration #3 | | 11.177 mi |
| Registration #4 | | 11.177 esi |
| Registration #5 | 2021-11-23 | 17.588 mi |
| | | |
| Registration #6 | | 11.777 est |
| Registration #6 Registration #7 | | 11.777 es |
| - | | 11.577 46 11.577 46 11.577 46 |
| Registration #7 | | 11.227 46 11.227 46 11.227 46 11.227 46 |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 80% |
| Pedestrian | 70% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1805 mm |
| Height | 1545 mm |
| Length | 4355 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1587 kg |
| Max. allowed weight | 1930 kg |
| Additional information | |
| Fuel tank capacity | 45 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G4LEJS326087 |