



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Silver
Year of manufacture	2005
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-17
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	46
Total items failed	6

MOT #18	2023-08-09 15:16
MOT test number	587054631522
Result	✓ Passed
Next expiry date	2024-08-08
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Central Front Items removed from driver's view prior to test
Advice	Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #17	2023-08-02 13:49
MOT test number	156210565531
Result	✗ Failed
Advice	Central Front Items removed from driver's view prior to test
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Fail	Nearside Front Lower Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #16**

2022-07-28 13:43

**MOT test number**

413453861737

**Result**

✓ Passed

**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #15**

2021-07-27 10:21

**MOT test number**

244098800270

**Result**

✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material n/o/s (1.1.11 (c))**Advice** Front Tyre worn close to legal limit/worn on edge n/o/s (5.2.3 (e))**Advice** Front Headlamp has a product on the light source but not seriously reducing light output n/o/s (4.1.4 (b))**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced n/o/s (6.1.1 (c) (i))**Advice** Front Tyre slightly damaged/cracking or perishing n/o/s (5.2.3 (d) (ii))**Advice** Front Brake pipe corroded, covered in grease or other material n/o/s (1.1.11 (c))**Advice** Brake disc worn, pitted or scored, but not seriously weakened front /rear n/o/s (1.1.14 (a) (ii))

**MOT #14**

2021-07-27 10:21

**MOT test number**

136223051429

**Result****✗ Failed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened front /rear n/o/s (1.1.14 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material n/o/s (1.1.11 (c))
- Advice** Front Headlamp has a product on the light source but not seriously reducing light output n/o/s (4.1.4 (b))
- Advice** Front Tyre worn close to legal limit/worn on edge n/o/s (5.2.3 (e))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced n/o/s (6.1.1 (c) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material n/o/s (1.1.11 (c))
- Advice** Front Tyre slightly damaged/cracking or perishing n/o/s (5.2.3 (d) (ii))
- Pass with rectification** Front Headlamp aim too low n/o/s (4.1.2 (a))

**MOT #13**

2019-01-29 15:17

**MOT test number**

213409517035

**Result****✓ Passed**

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake pipe corroded, covered in grease or other material o/s/n/s (1.1.11 (c))

**MOT #12**

2019-01-26 13:52

**MOT test number**

258206177491

**Result**

✗ Failed

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Rear Brake pipe corroded, covered in grease or other material o/s/n/s (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #11**

2018-01-05 09:58

**MOT test number**

188120536860

**Result**

✓ Passed

**Advice** Offside Front Items removed from driver's view prior to test phone holder**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #10**

2017-01-09 09:27

**MOT test number**

333431586631

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2016-01-07 11:21

**MOT test number**

349434174740

**Result**

✓ Passed

**MOT #8** 2016-01-07 09:11**MOT test number** 833009212589**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #7** 2015-01-13 11:15**MOT test number** 108243515094**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**MOT #6** 2013-10-29 13:51**MOT test number** 988572303324**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2012-11-29 12:29**MOT test number** 775394132364**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2011-12-20 15:29**MOT test number** 477984351402**Result** ✓ Passed



MOT #3	2010-12-31 09:43
MOT test number	322795060338
Result	✓ Passed

MOT #2	2009-12-29 10:50
MOT test number	363243969344
Result	✓ Passed
<div>Notice Child seat fitted not allowing full inspection of adult belt</div>	

MOT #1	2008-12-17 16:20
MOT test number	970992058397
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
8 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	8 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-12-30
Last registration	2023-08-09
Complete history	<a href="#">See info</a>



Registration #1	2005-12-30	12 mi
Registration #2	2008-12-17	31.180 mi
Registration #3	2009-12-29	37.492 mi
Registration #4	2010-12-31	43.312 mi
Registration #5	2011-12-20	49.504 mi
Registration #6	2012-11-29	53.132 mi
Registration #7	2013-10-29	55.671 mi
Registration #8	2015-01-13	59.440 mi
Registration #9	2016-01-07	62.799 mi
Registration #10	2016-01-07	62.799 mi
Registration #11	2016-01-07	62.799 mi
Registration #12	2016-01-07	62.799 mi
Registration #13	2016-01-07	62.799 mi
Registration #14	2016-01-07	62.799 mi
Registration #15	2016-01-07	62.799 mi
Registration #16	2016-01-07	62.799 mi
Registration #17	2016-01-07	62.799 mi
Registration #18	2016-01-07	62.799 mi
Registration #19	2016-01-07	62.799 mi
Registration #20	2016-01-07	62.799 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1490 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1CD0491619