



General information

Make	MINI
Model	MINI ONE
Colour	Red
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-11
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	42
Total items failed	4

MOT #14	2024-03-12 18:14
MOT test number	168120057060
Result	✓ Passed
Next expiry date	2025-03-11
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre slightly damaged sidewall has cut in outer sidewall (no cords) (5.2.3 (d) (ii))
Advice	Coolant level low
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement o/s + n/s lower arm rear bushes (5.3.4 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened slight corrosion too subframe (5.3.3 (b) (i))
Advice	Auxiliary drivebelt perished

**MOT #13**

2024-03-11 18:22

MOT test number

629933474300

Result**✗ Failed**

- Advice** Coolant level low
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre slightly damaged sidewall has cut in outer sidewall (no cords) (5.2.3 (d) (ii))
- Advice** TPMS light on
- Advice** Auxiliary drivebelt perished
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement o/s + n/s lower arm rear bushes (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened slight corrosion too subframe (5.3.3 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12

2023-03-01 10:56

MOT test number

937066963467

Result**✓ Passed**

- Advice** Offside front tyre damaged in side wall
- Advice** Auxillary drive belt perished
- Advice** Slight play in front wishbone rear bushes

MOT #11

2022-03-04 14:41

MOT test number

397997386706

Result**✓ Passed**

- Advice** Play in front wishbone rear bushes
- Advice** Offside rear tyre worn and perished

**MOT #10** 2021-03-04 10:21**MOT test number** 878481599540**Result** ✓ Passed**MOT #9** 2021-03-02 16:01**MOT test number** 107090787720**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2020-11-09 14:09**MOT test number** 710625598164**Result** ✓ Passed**Advice** Sill covers fitted**Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**Advice** Screen has small stone chips**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))**MOT #7** 2020-11-09 14:09**MOT test number** 694630481140**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Screen has small stone chips**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))**Advice** Sill covers fitted

**MOT #6** 2019-11-07 09:47**MOT test number** 285634156754**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front tyre wearing on edge**Advice** Screen has stone chips**Advice** Sill covers fitted**MOT #5** 2018-10-30 14:47**MOT test number** 786931139043**Result** ✓ Passed**Advice** Windscreen stone chipped**Advice** Sill covers fitted**MOT #4** 2017-11-09 10:50**MOT test number** 625147282469**Result** ✓ Passed**Advice** Brake pad(s) wearing thin Fronts - Inners (3.5.1g)**Advice** Plastic sill covers fitted**Advice** Brake pad(s) wearing thin Rears - Inners (3.5.1g)**Advice** Windscreen stonechipped



MOT #3	2016-11-22 10:09
MOT test number	102421447940
Result	✓ Passed
Advice	Plastic outer sill covers fitted
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #2	2015-11-23 13:29
MOT test number	641920401531
Result	✓ Passed
Advice	Cracking to both rear tyres
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Slight play both inner rackjoints

MOT #1	2014-11-27 12:23
MOT test number	365431834373
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
11 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	11 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-12-16
Last registration	2024-03-12
Complete history	See info



Registration #1	2011-12-16	19 mi
Registration #2	2014-11-27	35.124 mi
Registration #3	2015-11-23	45.041 mi
Registration #4	2016-11-22	52.616 mi
Registration #5	2017-11-09	58.945 mi
Registration #6	2018-10-30	65.171 mi
Registration #7	2019-11-07	69.275 mi
Registration #8	2020-11-09	72.085 mi
Registration #9	2021-11-09	75.277 mi
Registration #10	2022-11-09	78.277 mi
Registration #11	2023-11-09	81.277 mi
Registration #12	2024-03-12	84.277 mi
Registration #13	2024-03-12	87.277 mi
Registration #14	2024-03-12	90.277 mi
Registration #15	2024-03-12	93.277 mi
Registration #16	2024-03-12	96.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1160 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats 4

Engine number	A2201782
---------------	----------