



report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-05
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	36
Total items failed	4

MOT #17	2023-06-30 16:12
MOT test number	290844210567
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16	2022-06-30 16:51
MOT test number	615439606325
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2022-06-30 16:51
MOT test number	103292397879
Result	✗ Failed
Pass with rectification	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14	2021-07-01 14:32
MOT test number	895788212361
Result	✓ Passed

**MOT #13** 2021-07-01 11:43**MOT test number** 798336587505**Result** ✗ Failed**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**MOT #12** 2020-09-04 13:11**MOT test number** 539203507857**Result** ✓ Passed**MOT #11** 2020-09-04 13:11**MOT test number** 425826614262**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #10** 2019-12-20 09:40**MOT test number** 467220767836**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Exhaust system corroded

**MOT #9** 2018-12-21 11:03**MOT test number** 394535576984**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-12-21 09:45**MOT test number** 359763339833**Result** ✗ Failed**MAJOR** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2017-12-28 09:40**MOT test number** 614890820189**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)

**MOT #6** 2017-01-11 12:25**MOT test number** 551524339591**Result** ✓ Passed**Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**MOT #5** 2016-03-30 12:36**MOT test number** 867831868854**Result** ✓ Passed**MOT #4** 2015-03-20 10:13**MOT test number** 626359375077**Result** ✓ Passed**Notice** Advise tracking**Notice** Both front tyres worn on inner edge**MOT #3** 2014-03-26 14:38**MOT test number** 378005784028**Result** ✓ Passed**Notice** Both rear tyres have minor cracking to the outer walls**Advice** Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Notice** Exhaust backbox corroded but not to excess**Notice** Both windscreen wipers slightly deteriorated but still effective**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)



MOT #2 2014-03-18 09:06

MOT test number 787207474046

Result ✗ Failed

Advice Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

Notice Exhaust backbox corroded but not to excess

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Advice Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

Notice Both windscreen wipers slightly deteriorated but still effective

Notice Both rear tyres have minor cracking to the outer walls

MOT #1 2013-03-27 10:55

MOT test number 367716383031

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YR10YZU
Plate since	2019-03-29
Current registration	YR10YZU
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-31
Last registration	2023-06-30
Complete history	See info



Registration #1	2010-03-31	19 mi
Registration #2	2013-03-27	16.031 mi
Registration #3	2014-03-18	26.157 mi
Registration #4	2014-03-26	26.157 mi
Registration #5	2015-03-20	36.949 mi
Registration #6	2016-03-30	46.519 mi
Registration #7	2017-01-11	53.882 mi
Registration #8	2017-12-28	56.139 mi
Registration #9	2018-12-21	57.707 mi
Registration #10	2018-12-21	57.707 mi
Registration #11	2019-06-20	58.377 mi
Registration #12	2019-06-20	58.377 mi
Registration #13	2019-06-20	58.377 mi
Registration #14	2019-06-20	58.377 mi
Registration #15	2019-06-20	58.377 mi
Registration #16	2019-06-20	58.377 mi
Registration #17	2019-06-20	58.377 mi
Registration #18	2019-06-20	58.377 mi
Registration #19	2019-06-20	58.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5775203