






### General information

Make	HYUNDAI
Model	140 CRDI STYLE BLUE DRIVE
Colour	Blue
Year of manufacture	2014
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С







### Internet history

E	ntrv	1

Date Pictures 2021-05-25

35

Listing price

View report

B



source: autotrader.co.uk



### MOT history

MOT expiry date	2025-02-25
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #9	2024-02-26 16:18
MOT test number	579570751411
Result	✓ Passed
Next expiry date	2025-02-25

MOT #8	2023-02-03 08:51
MOT test number	535613044214
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not	seriously weakened (1.1.14 (a) (ii))

<b>MOT #7</b> 2	023-02-03 07:53
MOT test number	826265809046
Result	🗙 Failed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Fail Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))	
Advice Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
<b>Fail</b> Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

МОТ #6	2022-02-04 08:14
MOT test number	177783372083
Result	✓ Passed



E	K63WOB
	report date: 2024-03-28

MOT #5	2021-02-03 11:37
MOT test number	457245166624
Result	Passed
Advice All four tyres wearing on inner and outer edges	
MOT #4	2020-02-08 10:12
MOT test number	660973402483
Result	✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case of multip (4.7.1 (b) (i))	ble lamps or light sources
MOT #3	2019-02-05 10:08
	667402502000

MOT test	number 667402582808
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice (e))	Offside Front Tyre worn close to legal limit/worn on edge Nearing legal limit on inner edge (5.2.3
Advice	Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))
<b>Minor</b> (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (i))

MOT #2	2018-01-27 11:06
MOT test number	389115114023
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2017-02-11 10:35
MOT test number	664310232735
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 July 2024	✓ MOT Expires: 25 February 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 February 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	······································
Category	AMP
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
*********	
And a second sec	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-01-30
Last registration	2024-02-26
Complete history	See info



Registration #1	2014-01-30	8 mi
Registration #2	2017-02-11	29.838 mi
Registration #3	2018-01-27	45.764 mi
Registration #4	2019-02-05	64.474 mi
Registration #5	2020-02-08	81.780 mi
Registration #6	2021-02-03	93.159 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	D4FDEU412572