




report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D5 R-DESIGN NAV
Colour	Black
Year of manufacture	2014
Top speed	143 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-04
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #9 2024-04-26 14:40

MOT test number 199156747265

Result ✗ Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Items removed from driver's view prior to test
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #8	2023-04-28 10:17
MOT test number	596596610241
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))
Advice	Service warning light on
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	T,P,M,S Warning light on

MOT #7	2022-04-22 09:39
MOT test number	702511626121
Result	✓ Passed

MOT #6	2021-05-05 13:01
MOT test number	588724463290
Result	✓ Passed

MOT #5	2020-10-06 14:01
MOT test number	469598688553
Result	✓ Passed

MOT #4	2019-10-18 08:34
MOT test number	986373315250
Result	✓ Passed



MOT #3 2018-10-03 13:58

MOT test number 846138185558

Result ✓ Passed

MOT #2 2018-10-03 09:36

MOT test number 348390549782

Result ✗ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1 2017-09-25 09:37

MOT test number 577879616321

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
4 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KV64XZF
Plate since	2024-03-28
Current registration	KV64XZF
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-20
Last registration	2024-04-26
Complete history	See info



Registration #1	2014-10-20	29 mi
Registration #2	2017-09-25	19,813 mi
Registration #3	2018-10-03	21,732 mi
Registration #4	2018-10-03	21,732 mi
Registration #5	2019-10-18	24,869 mi
Registration #6	2020-10-06	26,509 mi
Registration #7	2021-10-06	28,149 mi
Registration #8	2022-10-06	29,789 mi
Registration #9	2023-10-06	31,429 mi
Registration #10	2024-04-26	33,069 mi
Registration #11	2024-04-26	34,709 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1521036