



**WJ070LR**

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE CLASSIC
Colour	Blue
Year of manufacture	2007
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	331 Nm at 1.800 rpm
Engine capacity	1.988 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-29
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-05-03
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	36
Total items failed	7

## MOT #18 2023-04-19 12:37

MOT test number 837312614331

Result ✓ Passed

Next expiry date 2024-05-03

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake hose slightly deteriorated NS&OS (1.1.12 (b) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush lower bush (5.3.2 (c))

## MOT #17 2023-04-19 11:29

MOT test number 638027973485

Result ✗ Failed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake hose slightly deteriorated NS&OS (1.1.12 (b) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush lower bush (5.3.2 (c))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #16** 2022-04-20 13:08**MOT test number** 258496233008**Result** ✓ Passed**MOT #15** 2021-05-04 15:23**MOT test number** 943718820606**Result** ✓ Passed**MOT #14** 2021-04-30 11:40**MOT test number** 483081105527**Result** ✗ Failed**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**Fail** Offside Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2020-04-30 10:27**MOT test number** 814438186915**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2019-04-26 11:58**MOT test number** 816998808056**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both sides front (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2019-04-24 13:39**MOT test number** 875544372674**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both sides front (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Brake pipe excessively corroded Both front to rear, on offside rear of vehicle (1.1.11 (c))**MOT #10** 2018-04-12 08:29**MOT test number** 235538518039**Result** ✓ Passed**MOT #9** 2017-03-23 16:32**MOT test number** 119894076434**Result** ✓ Passed**Advice** Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Brake pipe repaired, but not inappropriately (3.6.A.3)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2016-03-09 15:05**MOT test number** 460983702975**Result** ✓ Passed**Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #7** 2016-03-09 12:09**MOT test number** 212461505709**Result** ✗ Failed**Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2015-03-12 12:52**MOT test number** 649301775000**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Notice** Front brake discs worn/corroded on inner sides**MOT #5** 2014-02-25 14:48**MOT test number** 948936054055**Result** ✓ Passed

**MOT #4** 2013-03-05 15:41**MOT test number** 738504363010**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #3** 2012-02-29 10:40**MOT test number** 485450062084**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Drowning noise from vehicle**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2011-03-17 13:43**MOT test number** 206506871083**Result** ✓ Passed**MOT #1** 2010-03-24 15:37**MOT test number** 523763880046**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
3 May 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	3 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>WJ07OLR</b>
Plate since	2019-09-29
Current registration	<b>WJ07OLR</b>
Plate since	2019-09-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-01
Last registration	2023-04-19
Complete history	<a href="#">See info</a>



Registration #1	2007-03-01	16 mi
Registration #2	2010-03-24	32.559 mi
Registration #3	2011-03-17	40.639 mi
Registration #4	2012-02-29	48.567 mi
Registration #5	2013-03-05	56.984 mi
Registration #6	2014-02-25	66.776 mi
Registration #7	2015-03-12	74.302 mi
Registration #8	2016-03-09	82.843 mi
Registration #9	2016-03-09	82.844 mi
Registration #10	2017-03-23	93.716 mi
Registration #11	2018-03-20	105.557 mi
Registration #12	2019-03-20	117.397 mi
Registration #13	2020-03-20	129.237 mi
Registration #14	2021-03-20	141.077 mi
Registration #15	2022-03-20	152.917 mi
Registration #16	2023-03-20	164.757 mi
Registration #17	2024-03-20	176.597 mi
Registration #18	2025-03-20	188.437 mi
Registration #19	2026-03-20	200.277 mi
Registration #20	2027-03-20	212.117 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1575 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	0702100751396G