



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-1
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	421 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-20
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-08-24
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	33
Total items failed	1

MOT #11	2022-08-18 17:15
MOT test number	898812402776
Result	✓ Passed
Next expiry date	2023-08-24
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2022-08-17 07:42
MOT test number	926148900494
Result	✗ Failed
DANGEROUS	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
MAJOR	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9	2021-08-25 12:04
MOT test number	377317526577
Result	✓ Passed



MOT #8	2020-10-22 13:05
--------	------------------

MOT test number	751472463740
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #7	2019-10-26 10:01
--------	------------------

MOT test number	961464591575
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #6	2019-10-22 14:16
--------	------------------

MOT test number	980083580816
-----------------	--------------

Result	✗ Failed
--------	----------

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm inner part of center 3 quarters (5.2.3 (e))

MAJOR Power steering malfunctioning (2.1.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner part of center 3 quarters (5.2.3 (e))

MOT #5	2018-10-09 12:59
--------	------------------

MOT test number	374012926848
-----------------	--------------

Result	✓ Passed
--------	----------

**MOT #4**

2017-09-27 08:39

MOT test number

841304416885

Result

✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

2017-09-27 08:39

MOT test number

741239929776

Result

✗ Failed

- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #2** 2016-09-16 13:40**MOT test number** 792072406368**Result** ✓ Passed**Advice** Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2015-10-01 13:50**MOT test number** 624944073216**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear tyre has had a puncture repair**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Rear wiper blade split**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear tyre is cracking slightly



Tax & MOT check

X

Untaxed

Tax expired:
20 July 2023

X

MOT

Expired:
24 August 2023

Tax status	Expired at 20 July 2023
Days left	283 days too late
MOT expiry date	24 August 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	AF62KLZ
Plate since	2019-03-29
Current registration	AF62KLZ
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-12
Last registration	2022-08-18
Complete history	See info



Registration #1	2012-09-12	11 mi
Registration #2	2015-10-01	39.455 mi
Registration #3	2016-09-16	50.191 mi
Registration #4	2017-09-27	62.165 mi
Registration #5	2017-09-27	62.165 mi
Registration #6	2018-10-09	73.517 mi
Registration #7	2019-10-22	86.448 mi
Registration #8	2019-10-22	86.448 mi
Registration #9	2019-10-22	86.448 mi
Registration #10	2019-10-22	86.448 mi
Registration #11	2019-10-22	86.448 mi
Registration #12	2019-10-22	86.448 mi
Registration #13	2019-10-22	86.448 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1844 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBCH060659