



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT GTE ADVANCE DSG
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 100 km/h	7.6 seconds
0 - 60 mph	7.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	115 kW / 157 HP / 215 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.395 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	166.2 mpg
CO2 emission	40 g/km
CO2 label	A






## Internet history

### Entry 5


Date	2023-02-04
Pictures	26
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 4


Date	2022-11-23
Pictures	7
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 3

Date	2022-11-22
Pictures	7
Listing price	<a href="#">View report</a>




source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date	2022-02-17
------	------------

Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

### Entry 1

Date	2022-02-03
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2025-01-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	4
Total items failed	0

MOT #5	2024-01-20 11:40
MOT test number	568162385947
Result	✓ Passed
Next expiry date	2025-01-29

MOT #4	2023-01-30 08:52
MOT test number	239865212936
Result	✓ Passed

MOT #3	2022-01-26 12:19
MOT test number	749104005686
Result	✓ Passed

**Advice** Nearside Rear tyre sidewall cracked and perishing

MOT #2	2022-01-24 16:51
MOT test number	411800093439
Result	✗ Failed

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Nearside Rear tyre sidewall cracked and perishing

**MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))



MOT #1	2021-04-14 13:48
MOT test number	803430142250
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
29 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	29 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>First licence fee (12 months)</b>	£ 0,00,-
<b>Standard rate (12 months)</b>	£ 170,00,-
<b>Standard rate (6 months)</b>	£ 93,50,-
<b>Premium rate (12 months)</b>	£ 560,00,-
<b>Premium rate (6 months)</b>	£ 308,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-05-17
Last registration	2024-01-20
Complete history	<a href="#">See info</a>



Registration #1	2018-05-17	27 mi
Registration #2	2021-04-14	29.582 mi
Registration #3	2022-01-24	39.371 mi
Registration #4	2022-01-26	39.371 mi
Registration #5	2023-01-20	39.371 mi
Registration #6	2023-01-20	39.371 mi
Registration #7	2023-01-20	39.371 mi
Registration #8	2023-01-20	39.371 mi
Registration #9	2023-01-20	39.371 mi
Registration #10	2023-01-20	39.371 mi
Registration #11	2023-01-20	39.371 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1660 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CUKC118668