




report date: 2024-12-14

General information

Make	MINI
Model	COOPER D LONDON 2012 EDITION
Colour	Blue
Year of manufacture	2012
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2023-06-05
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2023-05-28
Pictures	9
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-06-27
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	31
Total items failed	11

MOT #16	2024-06-06 15:48
MOT test number	320053874178
Result	✓ Passed
Next expiry date	2025-06-27

MOT #15	2024-06-06 15:48
MOT test number	440306338698
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #14	2023-06-28 13:36
MOT test number	209171577038
Result	✓ Passed

MOT #13	2023-06-21 10:48
MOT test number	221669916886
Result	✗ Failed
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))



MOT #12	2022-09-02 09:54
MOT test number	401636068857
Result	✓ Passed

MOT #11	2021-08-26 13:11
MOT test number	130593682362
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2021-08-26 09:09
MOT test number	963801479773
Result	✗ Failed
Fail	Nearside Rear Lower Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen wiper blade defective (3.4 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2020-09-22 09:10
MOT test number	305611624859
Result	✓ Passed



MOT #8 2019-04-29 08:51

MOT test number 523286306177

Result ✓ Passed

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7 2019-04-26 09:35

MOT test number 157400746354

Result ✗ Failed

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #6 2018-04-16 12:44

MOT test number 704670369862

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #5 2018-04-16 09:00

MOT test number 631521422994

Result ✗ Failed

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Inner Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2017-04-28 14:36

MOT test number 311175263816

Result ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Front wipers smearing slightly
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #3 2016-04-29 16:05

MOT test number 231624710523

Result ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #2 2015-06-04 11:29

MOT test number 639495355182

Result ✔ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front wipers starting to split
- Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1 2015-06-04 11:29

MOT test number 536525455172

Result ✘ Failed

- Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front wipers starting to split
- Pass with rectification** Front Headlamp aim too low (1.8)
- Advice** Offside Inner Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2025

✓
MOT

Expires:
27 June 2025

Tax status	Valid until 1 June
Days left	133
MOT expiry date	27 June 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-01-01
Current registration	XXXXX
Plate since	2024-01-01

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-06-14
Last registration	2024-06-06
Complete history	See info



Registration #1	2012-06-14	26 mi
Registration #2	2015-06-04	23.037 mi
Registration #3	2016-04-29	31.860 mi
Registration #4	2017-04-28	39.165 mi
Registration #5	2018-04-16	48.564 mi
Registration #6	2018-04-16	48.564 mi
Registration #7	2019-04-26	58.428 mi
Registration #8	2019-04-29	58.428 mi
Registration #9	2020-09-22	70.140 mi
Registration #10	2020-09-22	70.140 mi
Registration #11	2020-09-22	70.140 mi
Registration #12	2020-09-22	70.140 mi
Registration #13	2020-09-22	70.140 mi
Registration #14	2020-09-22	70.140 mi
Registration #15	2020-09-22	70.140 mi
Registration #16	2020-09-22	70.140 mi
Registration #17	2020-09-22	70.140 mi
Registration #18	2020-09-22	70.140 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70368102