



PEUGEOT

**YB04MPF**

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ALLURE COUPE CABRIOLET
Colour	Silver
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg







Internet history

Entry 1

Date	2021-06-21
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #17</b>	2021-07-27 10:31
<b>MOT test number</b>	136711380855
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-07-26

<b>MOT #16</b>	2020-06-25 13:37
<b>MOT test number</b>	171281881443
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside front suspension arm ball joint dust cover insecure but still prevents the ingress of dirt
<b>Advice</b>	Offside outer drive shaft boot slightly deteriorated
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside front washer not working
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

<b>MOT #15</b>	2020-06-24 11:46
<b>MOT test number</b>	883776941423
<b>Result</b>	✗ Failed

**Fail** Front Registration plate inscription illegible (0.1 (b))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside front suspension arm ball joint dust cover insecure but still prevents the ingress of dirt

**Advice** Offside outer drive shaft boot slightly deteriorated

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Nearside front washer not working

**MOT #14** 2019-06-25 13:57**MOT test number** 906512913617**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Hand and foot brake only just met requirement,s**MOT #13** 2019-06-19 11:46**MOT test number** 411650458664**Result** ✗ Failed**Fail** Road wheel more than one fixing loose all 4 wheel,s wheel nut,s loose (5.2.1 (a) (ii))**Advice** Hand and foot brake only just met requirement,s**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2017-12-23 10:37**MOT test number** 103475080400**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 (3.5.1i)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #11**

2014-06-21 08:35

**MOT test number**

148912574115

**Result**

✓ Passed

**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2014-06-19 15:13

**MOT test number**

765160074167

**Result**

✗ Failed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2013-06-20 16:29

**MOT test number**

737631873104

**Result**

✓ Passed

**MOT #8** 2013-06-19 11:29**MOT test number** 358210673175**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2012-05-03 13:48**MOT test number** 457594822181**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #6** 2012-05-01 12:25**MOT test number** 588412322122**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2011-03-23 09:26**MOT test number** 399302481045**Result** ✓ Passed**Advice** Nearside Front Side repeater slightly discoloured (1.4.A.2f)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Offside Front Side repeater slightly discoloured (1.4.A.2f)



MOT #4	2010-03-20 11:13
MOT test number	944619770090
Result	✓ Passed
MOT #3	2009-04-03 12:52
MOT test number	124413199075
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
MOT #2	2008-04-04 08:56
MOT test number	712675198004
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
MOT #1	2007-04-13 13:02
MOT test number	720173607160
Result	✓ Passed





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>YB04MPF</b>
Plate since	2019-03-28
Current registration	<b>YB04MPF</b>
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-05-29
Last registration	2021-07-27
Complete history	<a href="#">See info</a>



Registration #1	2004-05-29	22 mi
Registration #2	2007-04-13	21.073 mi
Registration #3	2008-04-04	29.814 mi
Registration #4	2009-04-03	36.997 mi
Registration #5	2010-03-20	40.038 mi
Registration #6	2011-03-23	41.299 mi
Registration #7	2012-05-01	43.052 mi
Registration #8	2012-05-03	43.086 mi
Registration #9	2013-06-19	51.311 mi
Registration #10	2013-06-20	51.312 mi
Registration #11	2013-06-20	51.312 mi
Registration #12	2013-06-20	51.312 mi
Registration #13	2013-06-20	51.312 mi
Registration #14	2013-06-20	51.312 mi
Registration #15	2013-06-20	51.312 mi
Registration #16	2013-06-20	51.312 mi
Registration #17	2013-06-20	51.312 mi
Registration #18	2013-06-20	51.312 mi
Registration #19	2013-06-20	51.312 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1140 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	FX5N2427113