



**BG59XVD**

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Silver
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-10-16
<b>MOT pass rate</b>	85 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	12
<b>Total items failed</b>	3

<b>MOT #13</b>	2023-10-14 11:05
<b>MOT test number</b>	652577945857
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-10-16
<b>Advice</b>	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Engine cover/under trays/sill covers
<b>Advice</b>	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #12</b>	2022-10-01 10:34
<b>MOT test number</b>	950097979986
<b>Result</b>	✓ Passed
<b>Advice</b>	Engine cover/under trays/sill covers

<b>MOT #11</b>	2021-10-02 12:17
<b>MOT test number</b>	689498721024
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Engine cover/under trays
<b>Advice</b>	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2020-09-23 14:36**MOT test number** 645756398410**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened offside nearside (1.1.14 (a) (ii))**MOT #9** 2019-04-17 09:02**MOT test number** 876398937866**Result** ✓ Passed**Advice** Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #8** 2019-04-16 15:35**MOT test number** 136539831678**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #7** 2018-03-20 09:03**MOT test number** 852220999624**Result** ✓ Passed**Advice** Both rear tyres stepped**MOT #6** 2017-03-21 16:33**MOT test number** 973665833185**Result** ✓ Passed**MOT #5** 2016-03-15 10:30**MOT test number** 548638519348**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2016-03-15 10:30**MOT test number** 697186234428**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-03-10 09:49**MOT test number** 855989965040**Result** ✓ Passed**MOT #2** 2014-03-11 12:41**MOT test number** 478530174058**Result** ✓ Passed**MOT #1** 2013-03-20 18:23**MOT test number** 197339673420**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
16 October 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	16 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BG59XVD</b>
Plate since	2019-06-29
Current registration	 <b>BG59XVD</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-12-22
Last registration	2023-10-14
Complete history	<a href="#">See info</a>



Registration #1	2009-12-22	8 mi
Registration #2	2013-03-20	20.634 mi
Registration #3	2014-03-11	26.905 mi
Registration #4	2015-03-10	35.336 mi
Registration #5	2016-03-15	44.724 mi
Registration #6	2016-03-15	44.724 mi
Registration #7	2017-03-21	53.131 mi
Registration #8	2018-03-20	62.428 mi
Registration #9	2019-03-20	71.777 mi
Registration #10	2020-03-20	81.126 mi
Registration #11	2021-03-20	90.475 mi
Registration #12	2022-03-20	99.824 mi
Registration #13	2023-03-20	109.173 mi
Registration #14	2024-03-20	118.522 mi
Registration #15	2025-03-20	127.871 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 497918