





General information

| Make | VAUXHALL |
|---------------------|----------------------|
| Model | COMBO 2300 L2H1 CDTI |
| Colour | White |
| Year of manufacture | 2012 |
| Top speed | 97 mph |
| 0 - 60 mph | 15.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 1.500 rpm |
| Engine capacity | 1.248 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |







Internet history

Entry 1 Date

Pictures

2021-07-23

12

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-08-21 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 3 |
| Total items failed | 4 |

| MOT #11 2 | 023-08-22 10:35 |
|--|-----------------|
| MOT test number | 529199287086 |
| Result | 🗸 Passed |
| Next expiry date | 2024-08-21 |
| Advice Brake disc worn, pitted or scored, but not seriously weakened front (1.1.14 (a) (ii)) | |

| MOT #10 | 2022-07-02 08:59 |
|--|------------------------------|
| MOT test number | 203514124783 |
| Result | ✓ Passed |
| Advice Offside Front Upper Macpherson strut pin or bush worn but not res (5.3.4 (a) (i)) | ulting in excessive movement |

| MOT #9 | 2021-07-12 08:12 |
|--|------------------|
| MOT test number | 672325860775 |
| Result | 🗸 Passed |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #8 | 2020-08-25 13:53 |
|-----------------|------------------|
| MOT test number | 717977000826 |
| Result | ✓ Passed |





| MOT #7 | 2019-08-21 07:30 |
|-----------------|------------------|
| MOT test number | 172672653025 |
| Result | ✓ Passed |
| | |
| МОТ #6 | 2018-08-25 12:51 |
| MOT test number | 118839598035 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2010 00 25 10.55 |

| | 2018-08-25 10:55 |
|---|------------------|
| MOT test number | 176814318922 |
| Result | 🗙 Failed |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |

| MOT #4 | 2017-08-19 08:27 |
|-----------------|------------------|
| MOT test number | 120431934603 |
| Result | ✓ Passed |

| MOT #3 | 2016-08-20 09:30 |
|-----------------|------------------|
| MOT test number | 513240600906 |
| Result | ✓ Passed |

| MOT #2 | 2016-08-20 07:28 |
|---|------------------|
| MOT test number | 461999717821 |
| Result | 🗙 Failed |
| Fail Nearside Headlamp not working on dipped beam (1.7.5a) | |
| Fail Nearside Stop lamp not working (1.2.1b) | |
| Fail Offside Headlamp not working on dipped beam (1.7.5a) | |





| MOT #1 | 2015-08-24 11:03 |
|-----------------|------------------|
| MOT test number | 447817782992 |
| Result | ✓ Passed |



Tax & MOT check

| √ Taxed | мот |
|--|---|
| Tax due: 1 September 2024 Tax status | Expires: 21 August 2024 Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 21 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | |
| Category | L AMP |
| Туре | |
| Damage 2 | AMPLE |
| Date | 4 |
| Category | AMPL |
| Туре | |

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| AND | |
| | |
| | |
| ********** | |
| NUMBER OF CONTRACTOR OF CONTRA | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2012-07-31 |
| Last registration | 2023-08-22 |
| Complete history | See info |



| Registration #1 | 2012-07-31 | 17 mi |
|------------------|------------|------------|
| Registration #2 | 2015-08-24 | 36.321 mi |
| Registration #3 | 2016-08-20 | 46.073 mi |
| Registration #4 | 2016-08-20 | 46.073 mi |
| Registration #5 | 2017-08-19 | 57.569 mi |
| Registration #6 | 2018-08-25 | 64.304 mi |
| Registration #7 | 2018-08-25 | 64.304 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.117 mi |





Dimensions & weight

| Width | 2119 mm |
|---------------------|---------|
| Height | 1880 mm |
| Length | 4740 mm |
| Kerb weight | 1330 kg |
| Max. allowed weight | 2330 kg |
| | |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 2 |
| Engine number | 4682708 |