



report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Silver
Year of manufacture	-
Top speed	155 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	276 BHP
Max. torque	363 Nm at 4.800 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	17.5 mpg
Consumption extra urban	32.5 mpg
Consumption combined	24.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-05-13
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #23	2022-11-11 16:45
MOT test number	765914789765
Result	✓ Passed
Next expiry date	2023-11-10
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Minor	Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #22	2022-11-11 16:09
MOT test number	390148521506
Result	✗ Failed
Minor	Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #21	2021-11-09 09:27
MOT test number	643813993462
Result	✓ Passed

MOT #20	2021-11-09 09:27
MOT test number	501516161877
Result	✗ Failed
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #19** 2020-10-14 14:17**MOT test number** 938534366515**Result** ✓ Passed**MOT #18** 2020-10-13 09:59**MOT test number** 555443376178**Result** ✗ Failed

- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Nearside Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #17 2019-08-08 10:15**MOT test number** 922878950396**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Travel on handbrake lever

MOT #16 2019-08-08 10:15**MOT test number** 933984755193**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Travel on handbrake lever
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #15 2018-07-17 13:14**MOT test number** 467495191549**Result** ✓ Passed

**MOT #14** 2017-04-05 07:26**MOT test number** 829071073687**Result** ✓ Passed**MOT #13** 2017-04-01 10:24**MOT test number** 751544063373**Result** ✗ Failed

- Fail** Offside Rear Braking system leaking Caliper (3.6.A.1)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Exhaust catalytic converter missing where one was fitted as standard (7.1.3)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #12 2016-01-04 13:00**MOT test number** 155129658215**Result** ✓ Passed

- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #11 2015-12-29 09:16**MOT test number** 854476936688**Result** ✗ Failed

- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Offside Rear Braking system leaking calliper (3.6.A.1)

**MOT #10** 2014-09-12 13:23**MOT test number** 519565754249**Result** ✓ Passed**MOT #9** 2013-09-13 14:19**MOT test number** 348926753294**Result** ✓ Passed**MOT #8** 2012-07-03 11:21**MOT test number** 966145882197**Result** ✓ Passed**Notice** Nearside wiper blade torn slightly**MOT #7** 2011-07-06 15:32**MOT test number** 298727381418**Result** ✓ Passed**MOT #6** 2011-07-06 15:32**MOT test number** 608537481185**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2010-06-29 16:43**MOT test number** 810970180156**Result** ✓ Passed**MOT #4** 2009-07-09 16:55**MOT test number** 373210999182**Result** ✓ Passed



MOT #3	2008-03-31 16:46
MOT test number	892391198006
Result	✓ Passed
MOT #2	2007-03-29 13:08
MOT test number	381408087003
Result	✓ Passed
MOT #1	2007-03-29 09:58
MOT test number	580838287094
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	GK04KKL
Plate since	2019-03-28
Current registration	GK04KKL
Plate since	2019-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-04-10
Last registration	2022-11-11
Complete history	See info



Registration #1	2004-04-10	7 mi
Registration #2	2007-03-29	18.567 mi
Registration #3	2007-03-29	18.567 mi
Registration #4	2008-03-31	23.691 mi
Registration #5	2009-07-09	27.000 mi
Registration #6	2010-06-29	30.039 mi
Registration #7	2011-07-06	33.433 mi
Registration #8	2012-07-03	39.844 mi
Registration #9	2013-09-13	45.073 mi
Registration #10	2014-09-12	47.165 mi
Registration #11	2015-12-29	52.127 mi
Registration #12	2016-01-04	52.136 mi
Registration #13	2016-01-04	52.136 mi
Registration #14	2016-01-04	52.136 mi
Registration #15	2016-01-04	52.136 mi
Registration #16	2016-01-04	52.136 mi
Registration #17	2016-01-04	52.136 mi
Registration #18	2016-01-04	52.136 mi
Registration #19	2016-01-04	52.136 mi
Registration #20	2016-01-04	52.136 mi
Registration #21	2016-01-04	52.136 mi
Registration #22	2016-01-04	52.136 mi
Registration #23	2016-01-04	52.136 mi
Registration #24	2016-01-04	52.136 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1534 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	161051