





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|----------------------------|
| Model | I40 CRDI SE NAV BLUE DRIVE |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 124 mph |
| 0 - 60 mph | 12.0 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| Power | 139 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 1.700 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



OE65ACO report date: 2024-03-28

Internet history

Entry 2

Date 2021-12-31

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-12-30 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-01-06 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 9 |
| Total items failed | 0 |

| MOT #8 | | 2023-12-18 12:47 |
|--|--|------------------|
| MOT test r | number | 265990539525 |
| Result | | ✓ Passed |
| Next expir | y date | 2025-01-06 |
| Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #7 | 2023-01-04 11:52 |
|--|------------------|
| MOT test number | 568790950423 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge tread worn low and inner edge badly worn (almost to cords) (5.2.3 (e)) Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i)) | |

| MOT #6 | | 2023-01-04 10:53 |
|--|---|-----------------------------|
| MOT test | number | 507269424953 |
| Result | | X Failed |
| Advice | Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge tread worn low and inner edge badly worn (almost to cords) (5.2.3 (e)) | | and inner edge badly |
| MAJOR | Offside Front Steering rack gaiter missing or no longer prevents the ingres | ss of dirt (2.1.3 (g) (ii)) |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #5 | 2022-01-07 14:07 |
|--|------------------|
| MOT test number | 347443125911 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2020-12-22 16:43 |
| MOT test number | 957881037637 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2020-12-22 13:25 |
| MOT test number | 482997471814 |
| Result | × Failed |
| DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |

| MOT #2 | 2019-12-11 10:51 |
|--|------------------|
| MOT test number | 743033977014 |
| Result | ✓ Passed |
| Advice Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #1 | 2018-12-28 12:25 |
|-----------------|------------------|
| MOT test number | 557916971710 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 247 |
| MOT expiry date | 6 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
|--|-------------|
| | |
| THE STATE OF THE S | |
| | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | NK NK |
| Plate since | |
| Current registration | UK AIS |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2015-12-30 |
| Last registration | 2023-12-18 |
| Complete history | See info |



| Registration #1 | 2015-12-30 | 21 mi |
|------------------|------------|-----------|
| Registration #2 | 2018-12-28 | 20.240 mi |
| Registration #3 | 2019-12-11 | 24.605 mi |
| Registration #4 | 2020-12-22 | 26.850 mi |
| Registration #5 | 2020-12-22 | 26.850 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 19.777 mg |

More info >

CarCheck.co.uk page 10/11



OE65ACO report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 86% |
| Pedestrian | 43% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1815 mm |
|---------------------|---------|
| Height | 1470 mm |
| Length | 4775 mm |
| Wheel base | 2770 mm |
| Kerb weight | 1659 kg |
| Max. allowed weight | 2150 kg |

Additional information

| Fuel tank capacity | 70 |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11, |

Number of axles 2

Engine number D4FDFU573582