



report date: 2024-03-29

## General information

Make	VOLVO
Model	S40 S
Colour	Silver
Year of manufacture	2003
Top speed	121 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	121 BHP
Max. torque	170 Nm at 4.000 rpm
Engine capacity	1.783 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-04
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-30
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	32
Total items failed	1

MOT #21	2023-05-30 16:56
---------	------------------

MOT test number	511744951816
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-30
------------------	------------

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement track/camber perished (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement track/camber perished (5.3.4 (a) (i))

**MOT #20**

2023-05-30 10:43

**MOT test number**

655865274266

**Result****✗ Failed****MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement track/camber perished (5.3.4 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement track/camber perished (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #19**

2022-05-31 13:05

**MOT test number**

778518921914

**Result****✓ Passed****Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #18**

2021-05-05 08:41

**MOT test number**

612709236561

**Result****✓ Passed****Advice** Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement side arm bushes (5.3.4 (a) (i))**Advice** Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement side arm bushes (5.3.4 (a) (i))

**MOT #17** 2020-05-21 09:16**MOT test number** 315536561036**Result** ✓ Passed**MOT #16** 2019-05-17 15:26**MOT test number** 581942488661**Result** ✓ Passed**MOT #15** 2019-05-17 13:20**MOT test number** 582754289288**Result** ✗ Failed**MAJOR** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))**MAJOR** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))**MOT #14** 2018-05-24 14:19**MOT test number** 636991183640**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded front to rear pipe (3.6.B.2c)**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Rear Brake pipe slightly corroded front to rear pipe (3.6.B.2c)**MOT #13** 2018-05-14 09:05**MOT test number** 898450246291**Result** ✗ Failed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Rear Brake pipe slightly corroded front to rear pipe (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded front to rear pipe (3.6.B.2c)**Fail** Offside Rear coil spring broken (2.4.C.1a)

**MOT #12** 2017-05-15 08:17**MOT test number** 915536501548**Result** ✓ Passed**Advice** Offside Rear Outer Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #11** 2016-05-16 09:42**MOT test number** 671734277730**Result** ✓ Passed**MOT #10** 2015-05-18 09:24**MOT test number** 219608435480**Result** ✓ Passed**Notice** Osf tyre wearing edges**MOT #9** 2014-05-19 10:37**MOT test number** 377429034157**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #8** 2013-05-22 10:18**MOT test number** 599432143138**Result** ✓ Passed**MOT #7** 2012-05-21 11:01**MOT test number** 275252742143**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2011-05-16 09:13**MOT test number** 999526231107**Result** ✓ Passed**Advice** Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-05-13 12:38**MOT test number** 952673330145**Result** ✓ Passed**Notice** Wiper blades split**MOT #4** 2009-05-15 08:41**MOT test number** 664325039169**Result** ✓ Passed**MOT #3** 2008-05-14 11:45**MOT test number** 902135438153**Result** ✓ Passed**MOT #2** 2007-03-07 10:08**MOT test number** 821256567082**Result** ✓ Passed**MOT #1** 2006-03-16 15:18**MOT test number** 100685776428**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
30 May 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	30 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-03-28
Last registration	2023-05-30
Complete history	<a href="#">See info</a>



Registration #1	2003-03-28	18 mi
Registration #2	2006-03-16	8.368 mi
Registration #3	2007-03-07	10.216 mi
Registration #4	2008-05-14	11.516 mi
Registration #5	2009-05-15	12.600 mi
Registration #6	2010-05-13	13.846 mi
Registration #7	2011-05-16	15.640 mi
Registration #8	2012-05-21	16.621 mi
Registration #9	2013-05-22	18.109 mi
Registration #10	2014-05-19	19.778 mi
Registration #11	2015-05-18	22.430 mi
Registration #12	2016-05-16	25.013 mi
Registration #13	2016-05-16	25.013 mi
Registration #14	2016-05-16	25.013 mi
Registration #15	2016-05-16	25.013 mi
Registration #16	2016-05-16	25.013 mi
Registration #17	2016-05-16	25.013 mi
Registration #18	2016-05-16	25.013 mi
Registration #19	2016-05-16	25.013 mi
Registration #20	2016-05-16	25.013 mi
Registration #21	2016-05-16	25.013 mi
Registration #22	2016-05-16	25.013 mi
Registration #23	2016-05-16	25.013 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1716 mm
Height	1422 mm
Length	4516 mm
Wheel base	2562 mm
Kerb weight	1255 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	B4183140674