



General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Green
Year of manufacture	2012
Top speed	137 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-09-18
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-08-26
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	5

## MOT #12 2023-08-25 10:41

MOT test number 455300946156

Result ✓ Passed

Next expiry date 2024-08-26

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #11 2023-08-24 12:26

MOT test number 436651253272

Result ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Fuel pipe insecure (6.1.3 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

## MOT #10 2022-08-25 14:00

MOT test number 383768090541

Result ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

**MOT #9** 2022-08-25 09:03**MOT test number** 403666930663**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #8** 2021-08-27 14:52**MOT test number** 677257448684**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2020-11-11 17:18**MOT test number** 160202768343**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #6** 2019-10-18 09:13**MOT test number** 722930500215**Result** ✓ Passed**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**Advice** Front Brake pad(s) wearing thin approx 60-70% worn (1.1.13 (a) (ii))

**MOT #5** 2019-10-17 09:45**MOT test number** 374079051941**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin approx 60-70% worn (1.1.13 (a) (ii))**Fail** Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**Fail** Rear Registration plate insecure (0.1 (a))**MOT #4** 2018-10-23 15:47**MOT test number** 425702106337**Result** ✓ Passed**MOT #3** 2017-05-26 09:44**MOT test number** 382711333489**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Tyre worn close to the legal limit both rear and nearside front (4.1.E.1)**MOT #2** 2016-06-03 08:34**MOT test number** 403861199391**Result** ✓ Passed**MOT #1** 2015-06-02 10:07**MOT test number** 278173755472**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	26 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>RO12XBK</b>
Plate since	2024-03-28
Current registration	<b>RO12XBK</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-05-26
Last registration	2023-08-25
Complete history	<a href="#">See info</a>



Registration #1	2012-05-26	13 mi
Registration #2	2015-06-02	23.547 mi
Registration #3	2016-06-03	35.217 mi
Registration #4	2017-05-26	47.982 mi
Registration #5	2018-10-23	65.923 mi
Registration #6	2019-10-17	77.598 mi
Registration #7	2019-10-18	77.598 mi
Registration #8	2019-10-18	77.598 mi
Registration #9	2019-10-18	77.598 mi
Registration #10	2019-10-18	77.598 mi
Registration #11	2019-10-18	77.598 mi
Registration #12	2019-10-18	77.598 mi
Registration #13	2019-10-18	77.598 mi
Registration #14	2019-10-18	77.598 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1773 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1109863