



TOYOTA

X437VNO

report date: 2024-03-28

General information

Make	TOYOTA
Model	HI-ACE 2.4D LWB GS4DRTGP/V
Colour	Blue
Year of manufacture	2000
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	2.446 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-04-01
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	61
Total items failed	38

MOT #252021-03-29 10:24

MOT test number662795485156

Result✓ Passed

Next expiry date2022-04-01

- AdviceRear Outer both ns/os corroded
- AdviceRear Oil leak, but not excessive diff (8.4.1 (a) (i))
- AdviceNearside Rear Brake pipe corroded, covered in grease or other material along suspension arm (1.1.11 (c))
- AdviceUnderside off vehicle and suspension components generally corroded
- AdviceFront Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #24**

2021-03-20 09:57

MOT test number

279767600512

Result**✗ Failed****Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced step area (6.1.1 (c) (i))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Front washer jet n/w**Advice** Rear Oil leak, but not excessive diff (8.4.1 (a) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Underside off vehicle and suspension components generally corroded**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced chassis out rigger damaged/corroded (6.1.1 (c) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material along suspension arm (1.1.11 (c))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Outer both ns/os corroded**Fail** Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))



MOT #232020-04-02 13:28

MOT test number599364773593

Result

✓ Passed

Advice

Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice

Front number plate damaged

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice

Rear Brake pipe corroded, covered in grease or other material centre (1.1.11 (c))

Advice

Rear axle diff mount deteriorated

**MOT #22**

2020-03-25 12:29

MOT test number

763524944118

Result**✗ Failed**

- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Steering locking device missing track rod end (2.1.3 (d))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Front number plate damaged
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Offside Front Driver's door cannot be opened from inside the vehicle (6.2.3 (a))
- Advice** Rear axle diff mount deteriorated
- Fail** Front Seat belt anchorage loose centre inscure (7.1.1 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material centre (1.1.11 (c))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #21**

2019-03-30 08:57

MOT test number

691233617183

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front number plate damaged (cracked)
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Clutch pedal rubber missing
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #20

2019-03-28 12:11

MOT test number

219658532001

Result

✗ Failed

- Fail** Offside Rear Body panel corroded and likely to cause injury wheel arch (6.2.1 (a) (i))
- Advice** Front number plate damaged (cracked)
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Shock absorbers has an excessively worn bush lower bush (5.3.2 (c))
- Fail** Nearside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Clutch pedal rubber missing
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))

**MOT #19**

2018-03-29 11:21

MOT test number

404136974860

Result

✓ Passed

Advice

Nearside Front Outer Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #18

2018-03-27 08:46

MOT test number

707157209138

Result

✗ Failed

Fail

Rear Brake pipe excessively corroded underside just fowards from rear diff (3.6.B.2c)

Fail

Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm 195/70/15c (4.1.E.1)

Fail

Offside Rear Registration plate lamp not working (1.1.C.1d)

Fail

Offside Rear rear parking brake recording little or no effort (3.7.B.6a)

Advice

Nearside Front Outer Road wheel with a slightly distorted bead rim (4.2.A.1a)

Fail

Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

Fail

Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail

Offside Rear rear brake binding (3.7.B.1)

MOT #17

2017-03-11 09:21

MOT test number

288406032571

Result

✓ Passed

Advice

Offside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. service brake (3.7.B.5b)

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #16**

2017-03-11 09:21

MOT test number

548081196004

Result**✗ Failed**

Advice Offside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. service brake (3.7.B.5b)

Pass with rectification Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #15

2016-03-31 15:56

MOT test number

643856041551

Result**✓ Passed**

Advice Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)

Advice Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #14

2016-03-31 15:56

MOT test number

106582351940

Result**✗ Failed**

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)

Advice Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**MOT #13**

2015-04-04 10:23

MOT test number

377924995078

Result

✓ Passed

Notice Osr exhaust hanger corroded**Notice** Diff seal slight leak**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #12**

2013-12-02 17:30

MOT test number

536226833376

Result

✓ Passed

Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Osr exhaust supporting bracket broken temp repaired using cable ties**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11**

2012-11-26 08:45

MOT test number

149441432325

Result

✓ Passed

Advice Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Rear axel leaking oil**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)

**MOT #10** 2012-11-26 08:45**MOT test number** 818491332380**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Rear axel leaking oil**MOT #9** 2011-12-03 09:30**MOT test number** 746927331376**Result** ✓ Passed**MOT #8** 2011-11-17 13:45**MOT test number** 305411621366**Result** ✗ Failed**Fail** Offside Front Steering rack damaged and unserviceable (2.2.C.1d)**Fail** Rear registration plate deteriorated (6.3.1d)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2010-10-28 09:24**MOT test number** 152491600387**Result** ✓ Passed**MOT #6** 2009-10-23 13:31**MOT test number** 520376799237**Result** ✓ Passed



MOT #5	2008-10-28 09:09
---------------	------------------

MOT test number	354522008344
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2007-10-19 09:13
---------------	------------------

MOT test number	154222497275
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2007-10-19 09:13
---------------	------------------

MOT test number	961122097276
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)
--------------------------------	--

Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)
--------------------------------	--

MOT #2	2006-10-25 15:49
---------------	------------------

MOT test number	692058096214
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2005-10-13 16:50
---------------	------------------

MOT test number	222186785243
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✕
Untaxed

Tax expired:
15 July 2021

✕
MOT

Expired:
1 April 2022

Tax status	Expired at 15 July 2021
Days left	1018 days too late
MOT expiry date	1 April 2022
Full MOT history	See MOT history



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	X437VNO
Plate since	2024-03-28
Current registration	X437VNO
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2000-10-30
Last registration	2021-03-29
Complete history	See info



Registration #1	2000-10-30	6 mi
Registration #2	2005-10-13	80.949 mi
Registration #3	2006-10-25	93.928 mi
Registration #4	2007-10-19	103.539 mi
Registration #5	2008-10-28	113.742 mi
Registration #6	2009-10-23	126.078 mi
Registration #7	2010-10-28	138.172 mi
Registration #8	2011-11-17	144.458 mi
Registration #9	2011-12-03	144.458 mi
Registration #10	2012-11-26	149.715 mi
Registration #11	2013-12-02	156.951 mi
Registration #12	2015-04-04	164.436 mi
Registration #13	2016-03-31	171.189 mi
Registration #14	2016-03-31	171.189 mi
Registration #15	2016-03-31	171.189 mi
Registration #16	2016-03-31	171.189 mi
Registration #17	2016-03-31	171.189 mi
Registration #18	2016-03-31	171.189 mi
Registration #19	2016-03-31	171.189 mi
Registration #20	2016-03-31	171.189 mi
Registration #21	2016-03-31	171.189 mi
Registration #22	2016-03-31	171.189 mi
Registration #23	2016-03-31	171.189 mi
Registration #24	2016-03-31	171.189 mi
Registration #25	2016-03-31	171.189 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1650 mm
Kerb weight	1645 kg
Max. allowed weight	3000 kg

Additional information

Number of axles	2
Engine number	2L9609027